

Technical Service Bulletin (TSB)

Plant Mode Activated

REFERENCE:	TSB: 08-068-25 GROUP: 08 - Electrical	Date:	March 18, 2025	REVISION:	08-176-24
VEHICLES AFFECTED:	2024 (N4) RAM Rampage 2023 - 2025 (H1) Jeep Commander 2023 - 2025 (M1) Jeep Compass 2023 - 2025 (B1) Jeep Renegade - This bulletin applies to N4 vehicles built on or after November 01, 2023 (MDH 1101XX) and on or before April 04, 2024 (MDH 0404XX). - This bulletin applies to H1, B1 vehicles built on or after June 24, 2023 (MDH 0624XX) and on or before May 12, 2024 (MDH 0512XX). - This bulletin applies to M1 vehicles built on or after September 04, 2023 (MDH 0904XX) and on or before May 12, 2024 (MDH 0512XX).			MARKET APPLICABILITY: ☒ NA☐ MEA ☒ SA☐ IAP ☐ EE☐ CH	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs): - C170C-00 - PBC (Event PBC Factory Mode). - C1436-86 - Electric Parking Brake System Fail. - C10D0 - Electronic Park Brake System Failure. Customers may experience one or more of the following: - Vehicle does not accelerate properly. - Anti-Lock Brakes System (ABS) warning light on. NOTE: **The above Customer Symptoms are only applicable to vehicles with Plant Mode on.**				
CAUSE:	ABS module				

This bulletin supersedes Technical Service Bulletin (TSB) 08-176-24, date of issue August 02, 20243, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include a Customer Symptom Note, updated Failure Code, Diagnosis statement and Repair Procedure steps.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-111, date of issue August 02, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves replacing the ABS Module.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
05-40-07-98	ABS Module - Replace (0 - Introduction)	6 – Electrical and Body Systems	1.4 Hrs.
Failure Code	**ZY**	Service Action	

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	68721636AA - NA 7096764 - EMEA	BSM (ABS) Module	RENEGADE WITH TPMS 2 - PARA CONFERENCIA, PN CATALOGO: 6000633332
1 (AR)	68721644AA - NA 7096759 - EMEA	BSM (ABS) Module	FOR COMPASS MY23, MY24 AND MY25 PL8 - PARA CONFERENCIA, PN CATALOGO: 7093050
1 (AR)	68721648AA - NA 7096760 - EMEA	BSM (ABS) Module	FOR COMMANDER MY23 AND MY24 WITH ACC - PARA CONFERENCIA, PN CATALOGO: 7094340
1 (AR)	68721643AA - NA 7096761 - EMEA	BSM (ABS) Module	FOR COMMANDER MY25 WITH ACC - PARA CONFERENCIA, PN CATALOGO: 7094491
1 (AR)	68721635AA - NA 7096762 - EMEA	BSM (ABS) Module	FOR COMMANDER WITHOUT ACC - PARA CONFERENCIA, PN CATALOGO: 7094492
1 (AR)	68721637AA - NA 7096765 - EMEA	BSM (ABS) Module	FOR COMPASS MY23, MY24 AND MY25(NOT PL8) - PARA CONFERENCIA, PN CATALOGO: 7094699
1 (AR)	68721641AA - NA 7096766 - EMEA	BSM (ABS) Module	FOR RAMPAGE
1 (AR)	68417931AA - NA 68417931AA - EMEA	Break Fluid (500ML)	Warranty refund/ reimbursement only

DIAGNOSIS:

****This RSU only applies to vehicles on the RSU VIN list.****

REPAIR PROCEDURE:

1. ****Is the vehicle in Plant Mode?**
 - YES >>> Proceed to [Step 2](#).
 - NO >>> This bulletin does not apply. Normal diagnosis is needed.**
2. Replace the BSM (ABS) Module. Refer to the detailed service procedures listed in DealerCONNECT>Service Library>Service Info>under: 3340A12 - Centralina Hidraulica e Eletronica Do Circuito A.B.S - Remocao / Recolocacao Ou Substituicao. Ciclo Completo (Inclui Sangria).
3. Clear any DTCs that may have been set.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.