

Technical Service Bulletin

Topic	Engine overheating - Warning in the DIP (V8 Kovomo)
Market area	Bentley: worldwide (2WBE),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
Brand	Bentley
Transaction No.	2061369/9
Level	EH
Status	Released for publishing
Release date	Mar 17, 2025

New customer code

Object of complaint	Complaint type	Position
engine -> cooling, lubrication -> engine coolant temperature regulation	functionality -> faulty	
engine -> cooling system	functionality	
engine -> cooling system -> engine cooling fan wheel	noises, vibrations -> too loud	

Vehicle data

V8 Kovomo Engine

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S32CB	2020	E		*	*	*
3S32CB	2021	E		*	*	*
3S32CB	2022	E		*	*	*
3S32CB	2023	E		*	*	*
3S32CB	2024	E		*	*	*
3S34CB	2023	E		*	*	*
3S34CB	2024	E		*	*	*
3S42CB	2020	E		*	*	*
3S42CB	2021	E		*	*	*
3S42CB	2022	E		*	*	*
3S42CB	2023	E		*	*	*
3S42CB	2024	E		*	*	*
3S44CB	2023	E		*	*	*
3S44CB	2024	E		*	*	*
4V14D9	2018	E		*	*	*
4V14D9	2019	E		*	*	*
4V14D9	2020	E		*	*	*
4V14D9	2021	E		*	*	*
4V14D9	2022	E		*	*	*
4V14D9	2023	E		*	*	*
4V14D9	2024	E		*	*	*
4V14D9	2025	E		*	*	*
4V15D9	2024	E		*	*	*
4V15D9	2025	E		*	*	*
ZG22CB	2021	E		*	*	*
ZG22CB	2022	E		*	*	*
ZG22CB	2023	E		*	*	*
ZG22CB	2024	E		*	*	*
ZG24CB	2023	E		*	*	*
ZG24CB	2024	E		*	*	*
ZV14D9	2023	E		*	*	*
ZV14D9	2024	E		*	*	*
ZV14D9	2025	E		*	*	*

Documents

Document name
master.xml

Condition

One or a combination of the following symptoms are evident

- Engine overheat warning in the DIP (Engine overheating)
- Unusual cooling fan operation at high temperatures
- P19F700: Low engine coolant temperature indicator lamp coolant too warm
- Signs of coolant in the vacuum hoses for switch valve N649

Technical Background

To allow the engine coolant to heat as quickly as possible (from cold start) coolant delivery from the mechanical coolant pump is interrupted by switch valve N649

Figure 1 - Bentayga




Figure 1

Figure 2 - New Continental GT/ GTC and Flying Spur



Figure 2

NOTICE

The correct operation of N649 (Figure 3) is as follows

Un-energised state (Ignition off) - Coolant pump connected to vent connection (red arrows)

Energised state (Ignition on) - Engine vacuum connection to coolant pump (yellow arrows)




Figure 3

[Revision history - TPI 2061369/9](#)

The warranty instructions have been revised, and the thermostat is only advised to be replaced when the current part number fitted to the vehicle is level B or earlier.

The TPI has been updated to include the latest model years.

Production Solution

Should the issue be evident post the VIN's shown below please raise a technical DISS query and await feedback

New Continental GT/C and New Flying Spur

SCBBZ53S6MC087175

Bentayga

SJAAL14V0MC036042

Service

1) Disconnect each vacuum hose from N649 - Check for traces of coolant within the hoses - Refer also to the video on the Bentley Hub referencing TPI 2061369/-

Note: Take photos or record a video of any coolant in the vacuum hoses or N649 and attach to a new or existing DISS query for reference purposes

 **CAUTION**

DO NOT use compressed air to attempt to remove moisture from the vacuum lines (allow the moisture to evaporate) damage to other components and unintentional disconnection of vacuum hoses can occur if compressed air is used

Should moisture be evident or N649 does not hold vacuum the symptoms described are related to a defective coolant pump. To eliminate a repeat repair the operative must conduct the remaining instructions to completion

- Referring to Rep.Gr 19 - Replace parts listed below

 **NOTICE**

ONLY REPLACE THE COOLANT REGULATOR (THERMOSTAT) IF THE CURRENT PART NUMBER FITTED TO THE VEHICLE IS 0P2.121.115.B OR EARLIER

Coolant pump

Coolant regulator (Thermostat)

Switch valve for mechanical coolant pump N649



Ensure all procedures within the repair manual are followed regarding wheel alignment and calibrations to driver assist systems (Depending on vehicle specification)

- On completion conduct a road test to confirm the issue is resolved

Warranty

Warranty type 110 or 910

Damage service number 21 69

Damage code 00 17

[All Models](#)

Time to replace the switch valve for mechanical coolant pump solenoid N649

Labour operation code 19 85 19 22

Time 30 TU

Time to replace the Coolant regulator (Thermostat)

Labour operation code 19 58 19 71

Time 40 TU

Road test

Labour operation code 01 21 00 00

Time 50 TU

Time to replace the coolant pump (Depending on model)

Bentayga

87 34 19 20 - 860 TU - HVAC compressor remove/install (Includes front end module remove/install)

13 75 19 70 - 40 TU - Crank pulley remove/install

19 50 19 70 - 120 TU - Coolant pump remove/install (Includes regulator housing remove/install)

21 41 19 71 - 30 TU - Pressure pipe remove / install

24 34 19 71 - 20 TU - Throttle valve remove / install

New Continental GT / C

50 38 19 20 - 740 TU - Front end module remove/install

13 75 19 00 - 140 TU - Crank pulley remove/install

19 55 19 00 - 310 TU - Regulator housing remove/install

19 50 19 00 - 210 TU - Coolant pump remove/install

New Flying Spur

50 38 19 20 - 770 TU - Front end module remove/install

13 75 19 00 - 140 TU - Crank pulley remove/install

19 55 19 00 - 260 TU - Regulator housing remove/install

19 50 19 00 - 170 TU - Coolant pump remove/install



Due to various vehicle types and specifications the operative must refer to the Labour operations section within Elsa pro for Labour operation codes for the Wheel alignment and the alignment/calibration of all applicable Driver assist systems

Required Parts and Tools

New Continental GT / GTC and New Flying Spur

Description	Part number	Quantity
Switch valve N649	06H 906 283B	1

Bentayga

Description	Part number	Quantity
Switch valve N649	7PP 906 283F	1

All models

Description	Part number	Quantity
Coolant pump	0P2 121 014H	1
Coolant regulator (Thermostat)	Refer to ETKA	1
Coolant	Refer to ETKA	As required (Refer to Elsa Pro for quantities)



All part numbers listed are correct at the time of publishing, please always refer to the ETKA parts catalogue for latest part number information