

Instrument Cluster Message For Rear Turn Signal Lamp Despite Functioning Lights

Topic number	LI82.10-P-079175
Version	1
Function group	82.10 - Exterior lights
Date	4/21/25
Validity	Model series 253 facelift up to production date 10.10.2022 Model series 213 facelift up to production date 10.10.2022 Model series 167 up to production date 10.10.2022
Reason for change	

Complaint

Instrument cluster message for rear turn signal lamp despite functioning rear lamp.

Fault code in N10/8 - rear signal acquisition and actuation module in the quick test:

B164B49

The rear right turn signal lamp has malfunctioned. There is an internal electrical fault.

and/or

B164A49

The rear left turn signal lamp has malfunctioned. There is an internal electrical fault.

Cause

Sensitive fault detection in N10/8 - rear signal acquisition and actuation module (BC_R)

Remedy

1. Check rear lamp for failure of the individual LEDs

In the event that an LED fails, the rear lamp must be replaced
2. Check the software release of the Rear SAM (BC_R) and update if necessary
3. Add AO code "o70" via VeDoc
4. Perform SCN coding of Rear SAM (BC_R).
5. If concern occurred on left, use damage code 82C20 73

6. If concern occurred on right, use damage code 82R20 73

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms
Lighting > Exterior lights > Turn signal/hazard warning lights > Turn signal indicator > lit

Control unit/fault code	
Control unit	Fault text
N10/8 - Rear signal acquisition and actuation module (Rear SAM) (BC_R213)	B164A49 - The left rear turn signal lamp has a malfunction. There is an internal electrical fault.
	B164B49 - The right rear turn signal lamp has a malfunction. There is an internal electrical fault.

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
5	If occurs on left		82C20	Left
6	If occurs on right		82R20	Right