

April 18, 2025

Version 3

Warranty Extension: 2017 Odyssey 6AT Torque Converter–DTC P0741 Stored

Supersedes 23-077, dated November 17, 2023, to revise the information highlighted in yellow.

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2017	Odyssey	ALL w/ 6AT	Check the iN VIN status for eligibility

REVISION SUMMARY

Under BACKGROUND INFORMATION, warranty extension changed to 10 years or 150,000 miles.

BACKGROUND

Torque converters may not have been manufactured to proper specifications. As a result, the torque converter lock-up clutch cannot provide adequate holding force due to pressure bleeding down through a crack in the lock-up piston. The reduced lock-up clutch capacity results in the transmission indicator flashing “D” and set DTC P0741 Torque Converter Clutch Circuit Performance or Stuck OFF.

American Honda is extending the warranty on the torque converter to 10 years or 150,000 miles from the original date of purchase, whichever comes first.

CUSTOMER NOTIFICATION

Owners of affected vehicles will be sent a notification of this campaign.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

CORRECTIVE ACTION

Confirm the vehicle has DTC P0741 stored, then replace the torque converter.

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

PARTS INFORMATION

Part Name	Part Number	Quantity
Torque Converter Kit	06260-R9R-000	1
Split Pin (M14)	90701-S3V-A01	2
O-Ring (14.4X1.9)	91370-TA0-000	1
Flange Nut (12mm)	90371-SAA-010	4
Flange Bolt (10X35)	90163-SDA-A01	2
Flange Nut (12mm)	90362-SZA-A00	2
Flange Bolt (10X30)	95701-10030-08	3
Flange Bolt (12X30)	90161-SHJ-A00	2
Flange Bolt (14X125)	90165-TK8-A00	4
Castle Nut (14mm)	90363-S3V-A01	2
Flange Bolt (10X72)	90161-SHJ-A60	4
Flange Bolt (12X28)	90181-SK3-E00	4
Flange Bolt (10X30)	90163-SDB-A00	3

REQUIRED MATERIALS

Part Name	Part Number	Quantity
ATF DW-1 (1 qt)	08200-9008	5

WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2181BM	Replace Torque Converter (includes DTC clear and alignment)	5.7 hr	6T800	FFK00	A23077A	26000-R9R-315

Skill Level: Repair Technician

REPAIR PROCEDURE

1. Replace the torque converter assembly. *Refer to Automatic Transmission Removal and Installation* in Service Information.

NOTE:

- Overfilled transmission level can cause an overheat condition.
- Check the ATF level when the fluid temperature is greater than or equal to **80°C (176° F)**.
- If the fluid level is checked at a cooler temperature, it will read low or on the bottom dot of the dipstick.
- If the transmission fluid is filled to the top dot when cold, the transmission will be overfilled, increasing foaming and contributing to the overheating problem.

2. **Check ATF level**

Automatic Transmission Fluid Capacity at torque converter replacement.

4.5L (4.8 US qt)

COLD CHECK



HOT CHECK



END