



Bulletin No.: PIC6583D
Published date: 05/5/2025

Preliminary Information

PIC6583D U018B Set Current in One or More Modules

Models

Brand: Cadillac **Model:** LYRIQ **Model Years:** 2023 - 2025 **VIN:** from All to All **Engine:** All **Transmissions:** All

Involved Region or Country	North America, Middle East, Australia, New Zealand, Europe, Israel, Japan and S. Korea
Condition	A customer may comment one or more of the following concerns; NFC key card inop (My25 only), Service vehicle soon light, Service OnStar message.
Cause	K183 UHF module logic locked

Correction:

Perform a global reset by disconnecting 12V battery for 30 minutes, using Document ID: 6307865 Battery Negative Cable Disconnection and Connection.

If the K183 (UHF) module recovers from being offline, then the K183 will require the latest K183 24.169.1.3 or greater software to be flashed into the module, perform Vehicle Wide Programming, refer to [24-NA-113](#).

If the 12V battery reset does not recover the K183 offline issue, then K183 module replacement is required. In which service will install a new K183 at the latest K183 24.169.1.3 or greater release.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*6480028	System Reset	0.5
2819505	Vehicle Wide Programming	Use Published Labor Time
6430600	UHF Short Range Low Energy Remote Control Access Transceiver Replacement	Use Published Labor Time

Labor Operation	Description	Labor Time
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	5
Modified	10/25/2024 - Created on. 02/25/2025 - Updated correction. 03/25/2025 - Updated correction and Labor operation. 04/11/2025 - Updated Unique labor operation. 005/05/2025 - Updated Region and Correction.