



TECHNICAL SERVICE BULLETIN

Illuminated Powertrain Malfunction (Wrench) Indicator With DTC U1010 Stored In The SOBDMB

25-2321

16 July 2025

This bulletin supersedes 23-2292. Reason for update: update labor times associated with the Service Procedure from M-time to AP-time and add a cap.

Model:

Lincoln 2023 Corsair	Engine: 2.5L PHEV Built on or before 07-Sep-2023
--------------------------------	---

Markets: North American markets only

Issue: Some of the vehicle listed in the model statement above may exhibit an illuminated powertrain malfunction (wrench) indicator with DTC U1010 stored in the SOBDMB. This condition typically occurs after a plug-in charging event. This may be due to the software in the SOBDMB.

Action: For vehicles that meet all of the criteria in the Issue and Model statements, follow the Service Procedure to reprogram the SOBDMB.

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Service Part New Vehicle (SPNV)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SPNV/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2023 Corsair 2.5L PHEV: Retrieve DTCs And Perform Software Update On Appropriate Modules Following TSB Procedure (Do Not Use With Any Other Labor Operations)	AP252321A	AP Time Up to 0.5 Hrs.

Repair/Claim Coding

Causal Part:	RECAL
Condition Code:	04

Service Procedure

1. Connect a battery charger such as Rotunda GRX-3590 or DCA-8000 to the 12-volt battery.

NOTE: To prevent the battery saver mode from activating on the vehicle, make sure the negative cable of the charger is installed on a chassis or engine ground, and not the 12-volt battery negative terminal. Do not have the vehicle plugged in to a high voltage battery charger during programming. This can cause incorrect module programming. Make sure only the 12-volt battery charger is installed.

2. Download and run the "SOBDMB - Secondary On-Board Diagnostic Control Module B (SOBDMB) Software Update" application in the FDRS scan tool. Follow all on-screen instructions carefully to complete all required coordinated module software update(s), including:

- PCM
- SOBDMC
- ABS module
- BECM

© 2025 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.