

Uneven Engine Running as Well as Active Yellow Malfunction Indicator Light/Fault Memory Entry "P031600" in the DME Control Unit: Re-Programming DME Control Unit (87/25)

Vehicle Type: **911 S (992)**
911 4S (992)
911 GTS (992)
911 4 GTS (992)

Model Year: **As of 2020 up to 2024**

Country/Market: USA (C02)
 Canada (C36)
 Puerto Rico (C02/C0A)

Equipment: Emissions concept LEV3/TIER3 70 (M No. 7CE)
and
 7-speed manual transmission (M No. G1L/G1M)

Concerns: **DME control unit**

Cause: **The customer complains about uneven engine running during the warm-up phase and the lighting up of the yellow malfunction indicator light in the instrument cluster.**

The following fault memory entry is stored in the fault memory of the DME control unit:

- **P031600** - Misfire when the engine starts (first 1000 crankshaft revolutions) (0090D1)

Action: In the event of a customer complaint, re-programme the DME control unit using the PIWIS Tester.



Information

The minimum programming requirement is the PIWIS Tester software release: **43.600.020** (or higher).

Required tools

- Tools:
- **P90999 - PIWIS Tester 4**
 - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g. **VAS 5908 battery charger 90 A**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charging vehicle electrical system battery'*

Re-programming DME control unit

- 1 Re-programme DME control unit.

The basic work procedure for control unit programming is described in the Workshop Manual.

⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'

Specific information on control unit programming during this action:

Required PIWIS Tester software release:	43.600.020 (or higher)
Type of control unit programming:	Control unit programming using the ' Automatic programming ' function of the control unit. "Motor electronics (DME)" control unit – "Coding/programming" menu – " Automatic programming " function.
Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence. During the programming sequence, the DME control unit is re-programmed first, and then the transmission control unit is re-programmed. Both control units are then automatically re-coded . Do not interrupt the programming and coding process. Once the control units have been programmed and coded, you will be prompted to switch the ignition off and then back on again after a certain waiting time. Backup documentation of the new software releases are then performed.
Programming duration:	Programming takes up to 15 minutes , depending on equipment.
Data record programmed during this programming:	▪ DME control unit Software release: 0001 (or higher) Following control unit programming, the software release can be read out from the respective control unit using the PIWIS Tester in the menu ⇒ 'Extended identifications'.

Porsche part number (software) programmed during this programming:	911 S/4S (992): 992906020CQ 911 GTS/4 GTS (992): 992906022AM The specifications for the software release and Porsche part number (software) of the programmed record are based on the specified PIWIS Tester test software release. Please note that this may change in a later release.
Procedure in the event of error messages appearing during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'.</i>
Procedure in the event of a termination in the control unit programming:	Repeat control unit programming by restarting programming.

- 2 Read out and delete all control unit fault memories.
- 3 Exit the diagnostic application, switch off the ignition and disconnect **P90999 - PIWIS Tester 4** from the vehicle.
- 4 Switch off and disconnect the battery charger.
⇒ *Workshop Manual '270689 Charging vehicle electrical system battery'*

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
24702542	Re-programming DME control unit	

PCSS encryption:

Location (FES5)	24700	DME control unit
Damage type (SA4)	1134	Programming error

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.