



Connection offline

Technical Service Bulletin

Topic	01 MIL on, DTC P064F00 Stored in ECM
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2078914/2
Level	EH
Status	Released for publishing
Release date	Oct 15, 2025

New customer code

Object of complaint	Complaint type	Position
engine -> engine operation -> engine start	functionality -> no function	

Vehicle data

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
FU*	2025	A		DWV*	*	*
FU*	2025	A		DXB*	*	*
GU*	2025	A		DWV*	*	*

Documents

Document name
master.xml
attachment2.png



Technical Service Bulletin

01 MIL on, DTC P064F00 Stored in ECM

Transaction No.: 2078914/2

Release date: Oct 15, 2025

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added Model)
1	08/07/2025	Initial publication

Customer states:

Issue only occurs when performing diagnostic work in the workshop.

- Engine does not start
- MIL/ Exhaust emission warning lamp is on.

Workshop findings:

The following DTC is stored in the ECM, J623(address word 0001):

- Unauthorized software/coding detected **P064F00 active** (Refer to example V6 TFSI no coding)

[illegible]

DTC memory entry

Number:	P064F00: Unauthorized Software/Calibration Detected
Error type 2:	active/static
Symptom:	10529
Status:	10100111

Technical Background

The coding for the engine control unit may be lost during the ODIS diagnosis in the workshop. The precise cause is currently being analyzed.

Production Solution

Not applicable.

Service

To adapt the coding, the engine control unit must be replaced **virtually**. Please use the following functional check and delete the DTC **P064F00**:

Diagnostic address 0001 (engine control unit) – Replace engine control unit and code it.

Please note, the physical engine control unit does not need to be replaced. This is a virtual replacement.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0055		
Labor Operations:	GFF	0150 0060	Time stated on the diagnostic protocol
	GFF	0150 0010	See SRT with associated operations
Claim Comment:	As per TSB 2078914/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2078914**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.