

Technical Service Bulletin

Topic	45 DTC B2F0100, U012700, U112200, and/or U112300 is stored in the ABS control module
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2064758/5
Level	EH
Status	Released for publishing
Release date	Oct 17, 2025

Diagnostic trouble codes

Diagnostic address	Diagnostic trouble code	Fault symptom	Storage state
0003 - Brake electronics	B2F0100: Development code 1		static
0003 - Brake electronics	U012700: Lost Communication With Tire Pressure Monitor Module		Intermittent
0003 - Brake electronics	U112200: Data bus implausible message		Intermittent
0003 - Brake electronics	U012700: Lost Communication With Tire Pressure Monitor Module		static
0003 - Brake electronics	U112200: Data bus implausible message		static
0003 - Brake electronics	U112300: Data bus error value received		Intermittent
0003 - Brake electronics	B2F0100: Development code 1		Intermittent
0003 - Brake electronics	U112300: Data bus error value received		static

New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> warning display symbols -> brake failure warning display	functionality -> activates	
chassis -> brakes, brake regulation -> electronic stabilization control (ESC)	functionality -> no function	
chassis -> brakes, brake regulation -> anti-lock braking system (ABS)	functionality -> no function	
information, navigation, communication, entertainment -> indicator display symbols -> driving dynamics regulation (ESC) indicator display	functionality -> activates	
vehicle service -> vehicle diagnosis -> Guided Fault Finding (GFF)	control modules, services -> with fault stored in the DTC memory	
information, navigation, communication, entertainment -> malfunction display symbols -> ABS malfunction display	functionality -> activates	

Object of complaint	Complaint type	Position
chassis -> brakes, brake regulation -> electronic stabilization control (ESC)	functionality -> does not switch on/connect	

Vehicle data

Audi e-tron GT and Audi RS e-tron GT

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
F8*	2024	A		*	*	*
F8*	2025	A		*	*	*
F8*	2026	A		*	*	*
F83*	2022	A		*	*	*
F83*	2023	A		*	*	*

Documents

Document name
master.xml
vdm2064758_2.doc

Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header (Added Model Year)
4	09/10/2024	Revised header (Added Model Year) Revised <i>Warranty</i> (Removed Warranty Table)
3	11/02/2022	Revised header (Added Model Year) Revised <i>Condition</i> (Symptom Code modified)

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

- The ABS/ESC warning lamp may flash in the instrument cluster when the diagnostic tester is connected.

During PDI inspection the following DTCs may be logged in the ABS control module, J104 (address word 0003):

- **DTC B2F0100** (Development code 1) with symptom codes: 358656 (static) and 339457 (intermittent).

And/Or

- **DTC U012700** (Tire Pressure Monitoring Control Module - no Communication) with symptom code 358656 (static).

In addition to one or more of the above DTCs, the below DTCs may also appear:

- **DTC U112200** (Data bus implausible message) may be logged with symptom code 303616 (static).

And/Or

- **DTC U112300** (Data bus error value received) may be logged with symptom code 169984 (intermittent) and with symptom code 303360 (static).

NOTICE

The static DTCs cannot be erased. The intermittent DTCs can be erased but will be logged again as soon as the conditions for them occur.

Technical Background

The DTCs above are logged for design reasons (control module communication) but do not cause any issues for the customer. The function of the ABS/ESC is not altered or restricted by these DTCs.

Production Solution

Not applicable.

Service

No measure is necessary.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2064758**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.