

Vehicle-specific service

Topic	90 PSS HUD: Display disappears for approx. 7 seconds (DTC B1B68F0)
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2071758/4
Level	EH
Status	Released for publishing
Release date	Oct 22, 2025

Vehicle data

Audi Q4 vehicles

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
F4*	2022	A		*	*	*
F4*	2023	A		*	*	*
F4*	2024	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
WA1	*	FZ	*	P	*	000001	999999		
WA1	*	FZ	*	R	*	000001	999999		
WA1	*	FZ	*	N	*	000001	999999		

PR numbers

PR numbers
?:with KS3

Control units

Diagnostic address	Software part number	Software version	Hardware part number	Hardware version
005F - Information electronics 1	*89A*.035.*	3***	*	*

Documents

Document name
master.xml

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header (added SW Filter) Revised <i>Production Solution</i> (Removed production measure) Revised <i>Service</i> (changed solution)
3	07/02/2024	Revised <i>Technical Background</i> (provided more detail) Revised <i>Production Solution</i> (added production measure) Revised <i>Service</i> (changed solution) Revised <i>Warranty</i> (clarified warranty allowance)
2	02/20/2024	Revised header (added MY24, added SW Filter)

Customer states:

- The head-up display (HUD) image cuts out (disappears) for a short time (approx. 7 seconds).

Workshop findings:

The following DTC may be stored in the head-up display, -J898- (address word 0082):

- DTC B1B68F0:** Head-up display control module malfunction in display.

Technical Background

A software issue in the AR (Augmented Reality) creator causes this complaint. The AR Creator is a software component of the MIB (modular infotainment matrix) system. The image shown on the head-up display is generated in the AR Creator.

Production Solution

Not applicable.

Service



This TSB only applies if the head-up display displays an image again after approx. 7 seconds and without any additional customer intervention.

- Explain to the customer that the implementation of a measure is currently being analyzed. Analysis is expected to be completed in the first quarter of 2026.
- Do not replace any components for this condition since this will not resolve the customer's concern.
- Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi

(under *Related Links* >> *Service*).

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Do not replace parts or attempt repairs. Unjustified labor / replacement parts will be debited. **Invoicing under warranty is not permitted.**

Additional Information

All part and service references provided in this TSB (**2071758**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.