

Vehicle-specific service

Topic	91 PSS Various messages relating to driver assist systems, DTC U110100 logged in various control units
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2078209/2
Level	EH
Status	Released for publishing
Release date	Oct 24, 2025

Vehicle data

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
FU*	2025	A		*	*	*
GH*	2025	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
WAU	*	FU	*	S	N	000001	999999		
WAU	*	GH	*	S	A	000001	999999		

Documents

Document name
master.xml



Connection offline

Vehicle-specific service

Transaction No.: **2078209/2**

91 PSS Various messages relating to driver assist systems, DTC U110100 logged in various control units

Release date: Oct 24, 2025

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Adjusted Models)
1	06/09/2025	Initial publication

Customer states:

Various messages relating to driver assist systems malfunctions.

Workshop findings:

The customer statement can be reproduced.

The entry **“U110100: Component protection active, active/static, symptom: 1231633”** is logged in one or more event memories of the short-range radars (diagnostic addresses 8109, 810A, 810B, 810C) and/or adaptive cruise control units (diagnostic addresses 0013, 008B).

Technical Background

Due to a software issue in Electronic Central Electrical (BCM) control unit J519 (diagnostic address 0009), the component protection in the short-range radars is no longer deactivated.

Functional issues occur when component protection is active.

Production Solution

Production change in the fourth quarter of 2025.

Service



NOTICE

This PSS may apply to vehicles still in the new model launch repair authorization period!

- **For vehicles still in the launch phase, workshop must create a TAC case per the repair authorization in addition to entering vehicle in the PSS Database. Reference this TSB in the TAC case.**

1. If the customer's vehicle condition matches the condition listed in the *Technical Background* of this PSS TSB, explain to the customer that a solution is expected to be available by the end of the **4th quarter of 2025** (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

A solution is available for 2025 Q6 variants in TSB 2079729, 96 *Various messages relating to driver assist systems, event memory entry U110100 logged in various control units*.

Immediate measure in the workshop

Please perform a terminal 30 reset of Electronic Central Electrical (BCM) control unit J519 (diagnostic address 0009).

- Option 1: Use the current flow diagram to identify all fuses for Electronic Central Electrical (BCM) control unit J519 and remove them for at least 10 minutes.
- Option 2: Disconnect the vehicle battery for at least 10 minutes.

After a bus sleep cycle, the event memory can be deleted, and the complaint is temporarily resolved.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9710		
Damage Code:	0039		
Labor Operations:	GFF / Guided Functions	0150 0010	See SRT with associated operations
	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol
	(Option 1) Repair Electronic Central Electrical (BCM) control unit	9710 4199	10 TU
	(Option 2) Loosen and secure battery earth strap	9785 0950	See SRT with associated operations
Claim Comment:	As per TSB 2078209/2		

There is no reason to replace parts. If parts are replaced without good reason, they will be charged back.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2078209**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.