

ATTENTION:
GENERAL MANAGER ☐
PARTS MANAGER ☐
CLAIMS PERSONNEL ☐
SERVICE MANAGER ☐

IMPORTANT - All
Service Personnel
Should Read and
Initial in the boxes
provided, right.

© 2014 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2014-15MY Forester 2.0XT Turbo Models
SUBJECT: Reprogramming Files for DTC P0606 and
Extended Engine Cranking

NUMBER: 11-139-14

DATE: 05/16/14

INTRODUCTION

This bulletin announces the availability of ECM reprogramming for DTC P0606 on all 2014MY and some 2015MY 2.0 XT Turbo vehicles. In addition, reprogramming is now available for extended engine cranking on 2014MY 2.0 XT Turbo vehicles ONLY.

COUNTERMEASURE IN PRODUCTION

LOGIC CHANGE	INCORPORATED INTO PRODUCTION
Extended Engine Cranking	Start of 2015MY Production
DTC P0606	2015MY AFTER VIN F*409326

PACK FILE APPLICABILITY

EMISSION SPEC.	EMISSION SPEC.	TRANS. TYPE	PAK FILE NAME	NEW ECM PART NUMBER	OLD ECM PART NUMBER	NEW CID NUMBER
2014 Forester 2.0 XT Turbo	Fed / CAL	CVT	22611AW065.pak	22611AW065	22611AW060, 061, 062, 063, 064	AF56A00B
2015 Forester 2.0 XT Turbo			22765AG971.pak	22765AG971	22765AG970	LF61400B

SERVICE PROCEDURE / INFORMATION

NOTES:

SOA highly recommends connecting the Midtronics GR8 Diagnostic Battery Charger to the vehicle and utilizing the Power Supply Mode feature anytime a vehicle control module is being reprogrammed. Once the GR8 is connected to the vehicle, as long as the battery is fully charged, it takes less than 3 minutes to boot-up the charger, select the Power Supply Mode and have the battery voltage stabilized and ready for reprogramming.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

VERY IMPORTANT: This information is applicable to the Midtronics GR8 Diagnostic Battery Charger **ONLY**. It does not apply to any other brand / type of “generic” battery charger whatsoever. **ONLY** the GR8 and its Power Supply Mode feature has been tested and approved by Subaru of America, Inc. (SOA).

- If the GR8 indicates the vehicle’s battery must be charged, charge the battery using the GR8 before proceeding to reprogram the vehicle while using the Power Supply Mode.
- Control module failures as a result of battery discharge during reprogramming are not a matter for warranty. Should any DTCs reset after the reprogramming update is performed, diagnose per the procedure outlined in the applicable Service Manual.

WARRANTY / CLAIM INFORMATION

For vehicles within the Basic New Car Limited and / or Emissions Warranty period, this repair may be claimed using the following claim information:

LABOR DESCRIPTION	LABOR OPERATION #	FAIL CODE	LABOR TIME
MFI OBDII ECM Reprogramming	A455-288	UPG-48	0.4