

Technical Service Bulletin (TSB)
Rear Selective Thrust Washer Failure

REFERENCE:	TSB: 21-012-25 GROUP: 21 - Transmission and Transfer Case	Date:	January 21, 2025	REVISION:	—
VEHICLES AFFECTED:	2024 (D2) RAM 3500 Pickup 2024 (DJ) RAM 2500 Pickup This bulletin applies to vehicles built on or after June 14, 2024 (MDH 0614XX) and on or before September 04, 2024 (MDH 0904XX) equipped with the 6.7L I6 Cummins Turbo Diesel Engine (Sales Code ETL) and a 6-Spd Automatic 68RFE Transmission (Sales Code DG7).			MARKET APPLICABILITY: ☐ NA ☐ MEA ☒ SA ☐ IAP ☐ EE ☐ CH	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs): • P0218-00 - Transmission High Temperature Operation Activated. • P0716-00 - Input Speed Sensor 1 Circuit Performance. • P0729-00 - Gear 6 Shift Incorrect Ratio. • P0731-00 - Gear 1 Shift Incorrect Ratio. • P0732-00 - Gear 2 Shift Incorrect Ratio. • P0733-00 - Gear 3 Shift Incorrect Ratio. • P0734-00 - Gear 4 Shift Incorrect Ratio. • P0735-00 - Gear 5 Shift Incorrect Ratio. • P0841-00 - Transmission Fluid Pressure Sensor/Switch 1 Circuit Performance. • P0868-00 - Transmission Fluid Pressure Low. • P0871-00 - Transmission Fluid Pressure Sensor/Switch "C" Circuit Range/Performance. • P0876-00 - Transmission Fluid Pressure Sensor/Switch "D" Circuit Range/Performance. • P0944-00 - Loss Of Hydraulic Pump Prime. Customers may also comment on one or more of the following: • Hard shifting into gear. • Vehicle enters into limp home mode.				
CAUSE:	Rear selective thrust bearing cracking				

REPAIR SUMMARY:

This bulletin involves replacing the transmission.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
21-00-33-91	Transmission - Replace (3 - Highly Skilled)	21 - Transmission	3.2 Hrs.
Failure Code	ZZ	Service Action	

RELATED LOPS:

Labor Operation No:	Labor Description	Skill Category	Labor Time
21-00-19-67	4x4 Equipped (3 - Highly Skilled)	21 - Transmission	1.0 Hrs.
21-00-19-68	Skid Plate Equipped (3 - Highly Skilled)	21 - Transmission	0.1 Hrs.

SPARE PARTS:

Qty	Part No.	Description	Notes
1	K52109056AC	Automatic Transmission 68RFE	
6	K06508406AA	Torque Converter Bolts	
18	K68218057LA	Fluid, Auto Transmission ATF+4, Quart, Standard MS 9602-F	

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	-	
Disconnect Tool	9546	Essential Tool

REPAIR PROCEDURE:

1. Replace the transmission. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 21 - Transmission and Transfer Case / Automatic - 68RFE / Removal and Installation.
2. Using wiTECH, perform a Quick Learn Procedure.
3. Clear DTCs.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.