

Technical Service Bulletin (TSB)

Flash: Adaptive Cruise Control (ACC) Updates

REFERENCE:	TSB: 08-153-26 GROUP: 08 - Electrical	Date:	April 16, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (M1) Jeep Compass This bulletin applies to vehicles built on or before May 18, 2026 (MDH 0518XX) equipped with Adaptive Cruise Control W/Stop & Go (Sales Code NHZ).			MARKET APPLICABILITY: ☐ NA☐ MEA ☒ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the South America market.	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set the following Diagnostic Trouble Codes (DTC): - C14A4-00 - Sensor Adjustment Required. Customers may experience the following: "ACC/FCW Unavailable, Service Required" message in the Instrument Panel Cluster (IPC).				
CAUSE:	ACC software				

REPAIR SUMMARY:

This bulletin involves reprogramming the ACC with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-80-95-AC	Adaptive Cruise Control - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

1. Reprogram the ACC with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
3. Navigate to the ACC module "ECU view".
4. Select the "Misc Functions" menu.
5. Select the "ACC DASM Drive Calibration" procedure and follow the prompts provided in the diagnostic scan tool.

NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.