

Technical Service Bulletin (TSB)
Flash: Body Control Module (BCM) Update

REFERENCE:	TSB: 08-074-26 REV. A GROUP: 08 - Electrical	Date:	April 25, 2026	REVISION:	08-074-26
VEHICLES AFFECTED:	2026 (LB) Dodge Charger This bulletin applies to vehicles **built on or after March 27, 2025 (MDH 0327XX) and** on or before October 01, 2025 (MDH 1001XX) equipped with 400V G2500 FR/RR Elec Drive Motors (Sales Code ELD) and without Power Hatch (Sales Code JRC).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	**Technicians may find the following Diagnostic Trouble Code (DTC):** - B18AA-11 - Trunk/Gate Unlock Control 1-Circuit Short to Ground. NOTE: There are no Malfunction Indicator Lamp (MIL) illumination or related messages displaying in the Instrument Panel Cluster (IPC) for this symptom. Customers may comment on the following: - The hatch will not open when a release button (interior, exterior, or Frequency Operated Button Integrated Key (FOBIK)) is pressed.				
CAUSE:	BCM software				

This bulletin supersedes Technical Service Bulletin (TSB) 08-074-26, date of issue February 20, 2026, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an additional build date, LOP, updated Customer Symptom statement, Repair Summary statement, Diagnosis statement, Claims Data table, additional Repair Procedure steps and converting the bulletin to an RSU.

****This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-071, date of issue April 25, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.****

REPAIR SUMMARY:

****This bulletin involves inspecting and possibly reprogramming the BCM with the latest available software.****

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-02-J2	Module, Body Control - Inspect	6 - Electrical and Body Systems	0.2 Hrs.
18-19-02-JP	Module, Body Control - Inspect and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	RF	Required Flash - RSU	
	CC	Customer Concern	

The dealer must choose which failure code to use depending on if this is a Rapid Service Update(RSU) or Technical Service Bulletin.

- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RSU.
- The failure code “RF” (Required Flash) can no longer be used on Technical Service Bulletin flashes. The “RF” failure code must be used on an RSU.
- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.**

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer’s VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	—	—

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. **Is the vehicle on the RSU VIN list?
 - YES >>> Proceed to [Step 2](#).
 - NO >>> Proceed to [Step 3](#).
2. Does the BCM have the latest software already installed?
 - YES >>> This bulletin has been completed, use Inspect LOP (18-19-02-J2) to close the active RSU.
 - NO >>> Proceed to [Step 3](#).**

3. Reprogram the BCM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
4. Perform an ECU reset. Using the wiTECH, navigate to the Guided Diagnostics menu and select "Reset ECU".
5. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.