

Warning Message in Instrument Cluster: Fault Memory Entry "P060700 - Control Unit Reset" in The Front/Rear High-Voltage Power Electronics Control Unit (SY 31/26)

Model Line: **Taycan (Y1A/Y1B/Y1C)**

Model Year: **As of 2025**

Concerns: **Control unit for front high-voltage power electronics (A49)
Control unit for rear high-voltage power electronics (A50)**

Symptom: **A red/yellow warning message is displayed on the instrument cluster together with various fault memory entries.**

The following fault memory entry is stored in the fault memory of the front high-voltage power electronics (A49) or the rear high-voltage power electronics control unit (A50):

- **P060700** - Unexpected control unit reset (00AD16)

Remedial Action: Create vehicle analysis log (VAL) and check in the specified fault code under the **"fault memory entries"** tab whether the **"Initialization"** entry is stored in the field for **"Operating mode"**.

- **"Initialization"** is stored: Address the fault code entered using **"Guided Fault Finding"**.
- **"Initialization"** is **not** stored: The fault memory entry is **not** relevant for the specified complaint and can be ignored.



Information

If the entry **"Initialization"** is not stored, check which fault memory entry was stored at the time of the customer complaint using the time stamp of the other fault memory entries.

If the time of a fault memory entry corresponds to the occurrence of the customer complaint (e.g. if the yellow warning message lights up), continue the troubleshooting using this fault memory entry.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.