



Connection offline

Technical Service Bulletin

Transaction No.: **2073434/3**

93 Q4 electric drive: Power electronics: Powertrain fault - P0A6200/P0A6500/P0A5F00
- phase current U-V-W

Release date: Jun 30, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2022 – 2024	All	Not applicable

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Service</i> (Updated Solution) Revised <i>Warranty</i> (Updated labor operations)
2	07/27/2024	Revised <i>Service</i> (Updated Solution) Revised <i>Warranty</i> (Added Warranty table)
1	03/20/2024	Initial publication

Customer states:

Red warning light for electrical system fault lights up in instrument cluster. Vehicle does not start. Vehicle does not start after charging process.

Workshop findings:

The customer statement can be duplicated.

One or more entries for U, V or W phase faults are logged in the event memory under the diagnostic address 00CE with the following symptom numbers:

- **P0A5F00 and DFCC 41955:** Drive Motor "A" Phase U Current High
- **P0A6200 and DFCC 41933:** Drive Motor "A" Phase V Current High
- **P0A6500 and DFCC 41937:** Drive Motor "A" Phase W Current High

Technical Background

Software issue in control unit for electric drive motor/power electronics can lead to the described complaint occurring in extremely rare operating situations.

Production Solution

Not applicable.

Service

This TSB replaces Pending Service Solution (PSS) TSB 2071353: *93 Electric drive system - DTC: P0A6200/P0A6500/P0A5F00 - current phase U-V-W.*

A new software update for electric drive control unit 2 (-JX4- Diagnostic address 00CE) is required.

This TSB applies if one of the DTC entries specified above is logged in the relevant control unit together with the relevant symptom number.

Software solution for NAR

- 91EV (update ME3.2)
- 91FN (update ME3.2.1)
- TSB 2074069, *00 Q4 ME 3.5 Software update instructions* (update ME3.5)

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9340		
Damage Code:	0040		
Labor Operations:	Set-up and distribution time incl. charging the battery	0151 0010	20 TU
	Billing type: Flashing GFF 2.1 Connect diagnostic tester, perform flashing procedure No timestamp record required	0151 0061	Minus 20 percent in accordance with flash log
	Billing type: flash log Connect vehicle diagnostic tester, perform flashing procedure	0151 0060	Flash log
	Additionally for billing type flash log and flashing GFF 2.1 Bus sleep cycle and adaptation drive	0150 0099	30 TU
Claim Comment:	As per TSB 2073434/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2073434**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or

otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.