

Technical Service Bulletin (TSB)

Flash: DEF Dosing Control Unit (DCU) Software Updates

REFERENCE:	TSB: 08-285-26 GROUP: 08 - Electrical	Date:	July 18, 2026	REVISION:	—
VEHICLES AFFECTED:	2025 (DJ) RAM 2500 Pickup 2025 (D2) RAM 3500 Pickup 2025 (DD) RAM 3500 Cab Chassis 2025 (DP) RAM 4500/5500 Cab Chassis This bulletin applies to vehicles equipped with the 6.7L I6 Cummins HO Turbo Diesel Engine (Sales Code ETM).			MARKET APPLICABILITY: ☒ NA☐ MEA ☒ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North and South America markets.	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs): • P218F 00 - Reductant No Flow Detected • P202E 00 - Reductant Injection Valve Circuit Performance In addition, the following software enhancements are available: • System State feedback fix, data variant selection fix.				
CAUSE:	DCU software				

REPAIR SUMMARY:

This bulletin involves reprogramming the DCU software from 5.13 Or 5.14 To 5.15.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-18-9N	Module, DEF Dosing Control Unit (DCU) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the DCU with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The Helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

NOTE: For SA market only, after applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.