



Technical Service Bulletin

97 MMI display black and/or a parking brake malfunction, DTCs C100C01, U105400, U10B800, U10E200, and/or U10CA00

97 19 68 2057768/1 November 22, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7	2019	All	Not Applicable

Condition

Customer states:

One or more of the following concerns are present either intermittently or all the time:

- MMI does not come on or MMI screen remains black.
- Parking brake malfunction shown in instrument cluster.
- The parking brake cannot be released.

Workshop findings:

One or more of the following DTC(s) may be stored relating to the ABS control module, J104 (address word 0003), data bus on board diagnostic interface, J533 (address word 0019) and/or a failure in communication with the information electronics control module 1, J794 (address word 005F):

ABS control module:

- **DTC C100C01** (Electro-mechanical parking brake button Electrical error).

Data bus on board diagnostic interface:

- **DTC U105400** (Information electronics control module 1 No Communication).

Information electronics control module 1:

- **DTC U10B800** (Local data bus Faulty).
- **DTC U10E200** (Multimedia display unit 1 No communication).
- **DTC U10CA00** (Optical data bus for information electronics 1 Sporadic disruption).

Technical Background

The wire harness underneath the center console may be pinched during assembly.

Production Solution

Harness protection added underneath the center console.



Technical Service Bulletin

Service

If one or more of the customer concerns is present along with one or more of the faults listed above, inspect the harness underneath the center console for damage.

1. Remove the center console according to the repair manual.



Figure 1. Location to inspect underneath center console.



Technical Service Bulletin

2. Inspect the harness under the center console for damage as shown in Figures 1 and 2.




Figure 2. The harness is damaged during assembly.

3. If damage is found as shown in Figure 2, repair the damaged wires using VAS 1978B. Additionally, add the harness protection using the steps below.



Note:

If there is no damage present, continue with standard diagnosis. Ensure the harness is not pinched during re-assembly.

4. Once the damaged wires have been repaired with VAS 1978B, wrap the repaired section with the textile tape N 107 209 02.
5. Install the corrugated tube part number N 107 328 01 over the wrapped cables between the red lines indicated in Figure 3.



Technical Service Bulletin

6. Using textile tape N 107 209 02, completely wrap the corrugated tube over the harness so that it cannot slip out of place (red arrow on Figure 3).




Figure 3. Completed harness protection.

7. Use a new cable tie, part number **3D0 971 838 A** and secure the harness to the body (green arrow on Figure 3).
8. Once complete, refit the center console according to the repair manual.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9709		
Damage Code:	0024		
Labor Operations:	Remove and install console	6817 1900	See SRT
	Check central wiring harness	9709 0199	10 TU
	Repair central wiring harness (depends on number of damaged cables)	9709 41XX	See SRT
	Modify central wiring harness	9709 4999	20 TU
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 100 TU)
	Road test prior to the service procedure	No allowance	0 TU



Technical Service Bulletin

	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2057768/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

The part numbers mentioned in this TSB are different than the ones listed in ETKA. Only use parts listed in this TSB, this includes superseding part numbers!		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
N 10732801	Corrugated tube	.25
N 10720902	Textile tape	.1
3D0971838	Cable tie	01

Tool Number	Tool Description
VAS 1978B	Harness repair kit
VAS 61XX	ODIS Service with VAS tester

Additional Information

All part and service references provided in this TSB (2057768) are subject to change and/or removal. ©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.