

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: DTC P0942:49 TROUBLESHOOTING	Service Alert No.: SA-034/20
	Last Issued: 02/28/2020

APPLICABLE MODEL(S)/VINS

2016-2020 Mazda3
2016-2020 CX-5
2020 CX-30

DESCRIPTION

DTC P0942:49 is missing from the Workshop Manual on MGSS. Follow the repair procedure below to repair the vehicle until the information is added to the Workshop Manual.

REPAIR PROCEDURE

1. Verify customer concern.
2. Clear the DTC(s) and test drive the vehicle.
 - If DTC P0942:49 resets, replace the DSC H/U and test drive again.
 - If a different DTC is set during the test drive, diagnose the DTC using the information on MGSS.
 - If DTC P0942:49 does not reset, release the vehicle if no further DTC is set.
 - If a different DTC is set, diagnose the DTC using the information on MGSS.
3. Verify repair.

Page 1 of 1

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.