



Technical Service Bulletin

94 Rear lights do not switch from bumper to hatchgate after closing

94 20 24 2050234/4 April 21, 2020. Supersedes Technical Service Bulletin Group 94 number 19-02 dated February 7, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5	2018 - 2020	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header (Added MY 2020 and 2021) Revised <i>Production Solution</i> (Solution modified) Revised <i>Service</i> (Service procedure modified) Revised <i>Warranty</i> (Additional repair option SRT)
3	02/07/2019	Revised header (Added MY 2019 with VIN break) Revised <i>Production Solution</i> (Solution specified) Revised <i>Service</i> (Description of solution) Revised <i>Warranty</i> (Removed temporary solution) Revised <i>Required Parts and Tools</i> (Remove 'if necessary' statement)
2	07/17/2018	Revised <i>Warranty</i> (Updated Damage Code)

Customer may report:

- Brake light warning on in instrument cluster.
- When the rear lid is closed, the lights in the rear bumper do not switch over to the main lights on the rear lid.
- All of the rear light bulbs are fully functional. None are found to be faulty or incorrect.

Workshop findings:

The following DTC may be stored in the comfort system central control module, J393 (address 0046):

- **DTC B146C29** (Rear lid -closed- sensor implausible signal).



Technical Service Bulletin

Technical Background

When opening the rear lid on the Q5 the rear lighting changes from the rear lid to the bumper and when closing the rear lid the lighting changes back to the rear lid.

The two micro switches for the reverse light change-over are under the loading sill cover on the rear cross panel and are secured to the striker for the rear lid lock (Figure 1).

The following problems can occur:

1. The paddle on the micro switch was broken due to adjustment of the rear hatch or the striker in production.
2. Dirt can block one/both paddles on the micro switch, which is fastened to the striker of the rear lid (Figure 2).



Figure 1. Rear lid closed sensor.



Figure 2. Debris trapped in the rear lid closed sensor.



Technical Service Bulletin

Production Solution

- Adjustment of rear hatch optimized.
- The rear lid closed sensor assembly with additional enclosure to protect the switches from debris ingress is now installed. This improves the debris resistance of the switches but cannot eliminate it entirely.

Service

1. Replace the rear lid closed sensor if found broken (Figure 1).
2. If debris is found to be obstructing proper switch activation/deactivation, activate the switch paddles using your fingers and remove the debris. Using compressed air is effective.
3. Then check the measuring values for the G525 and G526 switches and replace the rear lid closed sensor if the malfunction persists. Only the improved rear lid closed sensor with the protective enclosure is available.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9661		
Damage Code:	0015		
Labor Operations:	Lock carrier cover remove + reinstall	7039 1900	See SRT
	Rear Lid Closed Sensor G525/G526 replacement	9661 1950	See SRT
	Or		
	Rear Lid Closed Sensor G525/G526 - repair	9661 9999	30 TU
Diagnostic Time:	GFF	0150 0000	20 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2050234/4		



Technical Service Bulletin

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Rear Lid Closed Sensor	01
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA

Additional Information

All parts and service references provided in this TSB (2050234) are subject to change and/or removal.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.