



Technical Service Bulletin

01 MIL on, DTC P013A00 stored in the ECM

01 20 64 2059514/1 May 19, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5	2018	All	2.0

Condition

Customer states:

- MIL on.

Workshop findings:

One or more of the following DTC(s) is stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P013B00** (O2 Sensor Bank1-Sensor 2 slow response – Lean to Rich).
- **DTC P013A00** (O2 Sensor Bank1-Sensor 2 Slow Response - Rich to Lean).

Technical Background

Updated software in the engine control module will correct the condition.

Production Solution

Updated software in the engine control module (ECM), J623 (address word 0001) addressed the condition.

Service



Note:

Parts replacement does not solve this issue, claims for replaced parts will not be reimbursed.

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the engine control module (ECM), J623 (address word 0001) using the SVM action code as listed in the table below, if necessary:



Technical Service Bulletin

Model	Engine	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
Q5	2.0 TFSI	80A906259A	0001-0003	80A906259A	0004	01A209

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2059514/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions*.

All part and service references provided in this TSB (2059514) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of



Technical Service Bulletin

Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.