



Technical Service Bulletin

01 MIL on, DTCs P030100, P030200, and/or P030300 are stored in the ECM

01 20 81 2060491/1 August 26, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2019	All	3.0 TFSI

Condition

Customer states:

- MIL on.
- The idle speed is erratic.

Workshop findings:

- For a single cylinder misfire DTC this bulletin does not apply, continue diagnosis outside of this TSB.

At least two of the following DTCs are stored in the engine control module (ECM), J623 (address word 0001) and occur at the same time:

- **DTC P030100** (cylinder 1 misfire).

And/or

- **DTC P030200** (cylinder 2 misfire).

And/or

- **DTC P030300** (cylinder 3 misfire).

Technical Background

With a fully loaded activated charcoal filter reservoir and high outside temperatures the discharge point of the fuel vapor on bank 1 can cause multiple cylinders misfiring. This occurs only on bank 1 because of a too rich mixture.

Production Solution

New software in the ECM, J623 (address word 0001) addressed the condition.



Technical Service Bulletin

Service

This TSB replaces Pending Service Solution (PSS) TSB 2054113: *PSS 01 Bank 1 engine misfires - A8*.

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the ECM, J623 (address word 0001) using the SVM action code as listed in the table below, if necessary:

Model	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
A8	4N0907559B	0002 0003 0004 0005	4N0907559B	0007	01A255

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • 1E1 up to 8 Years/80,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 60 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2060491/1		



Technical Service Bulletin

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions*.

All part and service references provided in this TSB (2060491) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.