



NUMBER: 18-056-16

GROUP: Vehicle Performance

DATE: May 07, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-082-15 DATED NOVEMBER 05, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES ADDITIONAL DIAGNOSTIC TROUBLE CODE (DTC) FOR 2015 WD & WK, MARKET INFO AND NEW LOP.**

FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: Powertrain Diagnostic and System Improvements

OVERVIEW:

This bulletin involves reprogramming the Powertrain Control Module (PCM) with the latest available software.

MODELS:

2015	(WK)	Jeep Grand Cherokee
2014-2015	(WD)	Dodge Durango

NOTE: This bulletin applies to 2015 WD and 2015 WK vehicles within the following markets/countries: **NAFTA****,LATAM, EMEA or APAC**

NOTE: **This bulletin applies to 2015 WK and WD vehicles equipped with a 3.0L V6 24V VVT Engine (Sales Code EHD) or 5.7L V8 MDS VVT Engine (Sales Code EZH).******

NOTE: This bulletin applies to 2014 WD vehicles equipped with a 5.7L engine (Sales Code EZH) built on or before October 9, 2014 (MDH 1009XX).

SYMPTOM/CONDITION:

The following powertrain system improvements/enhancements are included in this software release. These symptoms are broken down by vehicle:

2015 WK 3.0L engine (Sales Code EHD)

- ** P0456 - EVAP System Small Leak.**
- Enhancements to remote engine start.

2015 WK 5.7L engine (Sales Code EZH)

- ** P0456 - EVAP System Small Leak.**
- U0140-00 - Lost Communication with Body Control Module (BCM).
- Enhancements to improve a slight lag or hesitation during Multi Displacement System (MDS) mode transitions.
- Enhancements to improve a slight drop in engine RPM when the vehicle is shifted to reverse or drive within 3 seconds of a cold start.

2014 WD 5.7L engine (Sales Code EZH)

- Enhancements to improve a slight drop in engine RPM when the vehicle is shifted to reverse or drive within 3 seconds of a cold start.

2015 WD 5.7L engine (Sales Code EZH)

- ** P0456 - EVAP System Small Leak.**
- Enhancements to remote engine start.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition or if the technician finds the DTC listed above, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allows them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-06-JR	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1- Engine Repair and Performance	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 3 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use. If the customer came in with an issue and if the dealer finds a software update to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash