



Technical Service Bulletin

94 Headlamp warning is displayed in cluster, DTC C119911 is stored in the left and/or right light control module

94 21 38 2063125/1 May 19, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Audi e-tron quattro, Audi e-tron Sportback	2021	00001 - 033000	Digital matrix lighting

Condition

Customer states:

- A warning message is displayed in the instrument cluster regarding the headlights.

Workshop findings:

- The headlight operation is not affected.

The following DTC is stored in the left light control module, J1018/A27 (address word 00D6) and/or right light control module, J1023/A31 (address word 00D7):

- **DTC C119911** (High beam bulb, short circuit to ground).

Technical Background

The diagnostic software is too sensitive.

Production Solution

New software installed for production.

Service



Applies to vehicles with high-voltage components:

To prevent charging of the high-voltage battery during the software update, the high-voltage charging cable is to be removed **BEFORE** entry of the SVM code on vehicles with high-voltage components.



Technical Service Bulletin

Charging the high-voltage battery during a software update can lead to damage to the high-voltage components.

1. Ensure the concern and DTC described above match and no other root causes are present.

SVM Update Instructions

2. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
3. Update the left and right light control module, J1018/A27 and J1023/A31 (address words 00D6 and 00D7) using the SVM action code as listed in the table below, if necessary:

Model	Old Target Data Container Number	Old Target Data Container Version	New Target Data Container Number (or higher)	New Target Data Container Version (or higher)	SVM Code Input
Audi e-tron quattro, Audi e-tron Sportback	4KE909472F	*	4KE909472H	*	D6A010

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9407		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
Diagnostic Time:	GFF	No allowance Included above	0 TU
	Road test prior to the service procedure	No allowance	0 TU



Technical Service Bulletin

	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2063125/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions*.

All part and service references provided in this TSB (2063125) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.