



Technical Service Bulletin

PSS 91 SOS emergency call malfunction, DTC B129B13 and B129C13 are stored in the emergency call control module

91 22 79 2061626/2 February 18, 2022. Supersedes Technical Service Bulletin Group 91 number 20-44 dated December 9, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5 Cabriolet	2020	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	--	Revised service (updated expected release date)
1	12/09/2020	Initial publication

Customer states:

- The message "SOS – Emergency call malfunction, please contact service" is displayed in the instrument cluster.

Workshop findings:

The following DTCs are stored in the control module for the emergency call module and communication unit, J949 (address word 0075):

- DTC B129B13** (microphone 1, open circuit).
- DTC B239C13** (microphone 2, open circuit).

Technical Background

A software malfunction can cause the aforementioned DTCs to be entered erroneously.

Production Solution

Not applicable.

Service

1. Clear the DTCs.



Technical Service Bulletin

2. Explain to the customer that a solution is forthcoming in the 3rd quarter of 2022 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Access Audi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa. Warranty

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9170		
Damage Code:	0039		
Diagnostic Time:	GFF	0151 0000	Time stated on the diagnostic protocol (Max 25 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2061626/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2061626) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin
