



NUMBER: 18-010-13

GROUP: Vehicle Performance

DATE: March 06, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE LEVEL MUST BE AT RELEASE 13.03 OR HIGHER TO PERFORM THIS PROCEDURE.

SUBJECT:

Flash: MIL Illumination P0340- Camshaft Position Sensor Circuit - Bank 1 Sensor 1

OVERVIEW:

This bulletin involves selectively erasing and reprogramming the Powertrain Control Module (PCM) with new software.

MODELS:

2011 - 2012 (LC) Challenger

NOTE: This bulletin applies to vehicles equipped with a 5.7L engine (sales code EZC) or 6.4L engine (sales code ESH) and equipped with a 6 Speed manual transmission (sales code DEC).

SYMPTOM/CONDITION:

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the Technician may find that the following Diagnostic Trouble Code (DTC) has been set:

- P0340 - Camshaft Position Sensor Circuit - Bank 1 Sensor 1

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTC's other than the ones listed above are present, record them on the repair order and repair as necessary before proceeding further with this bulletin.

1. Is DTC P0340 stored in the PCM?
 - a. Yes>>> Proceed to Step 2.
 - b. No>>> No further action necessary, bulletin does not apply.
2. Access the Freeze Frame Data for DTC P0340 and view the stored Engine RPM. Is the displayed RPM 500 or less?

- a. Yes>>> Perform Repair Procedure.
- b. No>>> Bulletin does not apply. Continue normal diagnostics for this DTC.

PARTS REQUIRED:

Qty.	Part No.	Description
1	04275086AD	Label, Authorized Modification

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Follow the detailed service procedures available in DealerCONNECT/TechCONNECT, Refer To Group 8 - Electrical > Electronic Control Modules - Service Information > Module - Powertrain Control > Standard Procedures > PCM/ECM Programming.
2. **After PCM reprogramming, the following must be performed:** clear any DTC's that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.
3. Type the necessary information on the "Authorized Modification Label" and attach it near the VECI label.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
18-19-06-T7	Module, Powertrain Control (PCM) - Reprogram (1 - Semi-Skilled)	0.2 Hrs.

FAILURE CODE:

FM	Flash Module
----	--------------