



NUMBER: 08-053-14 REV. A

GROUP: Electrical

DATE: July 03, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 08-053-14, DATED JUNE 11, 2014 WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE CHANGING THIS SERVICE BULLETIN TO AN RRT STATUS.**

****THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-050. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY**.**

USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING "HELP" THEN "HELP CONTENTS" AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE LEVEL MUST BE AT 14.03 OR HIGHER TO PERFORM THIS PROCEDURE.

SUBJECT:

Flash: Vehicle Enhancement

OVERVIEW:

This bulletin involves updating the Body Control Module (BCM) software.

MODELS:

2014	(WK)	Grand Cherokee
2014	(WD)	Durango

NOTE: This bulletin applies to vehicles built on or before May 06, 2014 (MDH 0506XX).

SYMPTOM/CONDITION:

The customer may experience one or all of the following:

- False security alarm activation.
- A significant delay to update the ambient air temperature display.
- Intermittently the interior lights may not turn on with the first press of the key fob.

- Ambient temperature may display - 40 F/-40 C for a few seconds at start up.
- Courtesy lamps are dim when approaching the vehicle after a remote start.
- Intermittently the vehicle may not start, after the vehicle has been driven and then trying to restart the vehicle with remote start.
- Back lighting flickers after a remote start, the condition is gone after entering the vehicle and restarting it.
- Engine may turn off, after the vehicle is remote started and then unlocking the vehicle with the liftgate passive entry.
- False U0422-00- Implausible Data Received and turning on the MIL indicator lamp. **(Diesel Only)**
- Missing DTCs for open or short cabin heater 1, 2 or 3. **(Diesel Only)**
- False DTC setting for front Daytime Running Lamps (DRL) circuit open, DRL will work properly.
- False setting for B16D3-15 Right DRL Lamp Control - Circuit Short To Battery Or Open.
- False setting for B16CF-15 Left DRL Lamp Control - Circuit Short To Battery Or Open.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify no DTCs are set other than the ones listed above. If DTCs are present, record them on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describes the symptom/condition or if the technician finds the DTCs, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted or failed, the flash should be restarted.

1. Reprogram the BCM.
2. Flash reprogram the module . Using the wiTECH Diagnostic Application for flashing the module is made available through the wiTECH Diagnostic Application. For instructions select the "HELP" tab on upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
3. Turn off the vehicle and let the Communication Buss go to sleep, this may take over a minute before the Buss goes to sleep. This will cause all active DTC to go stored. Clear any DTCs that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-02-P9	Module, Body Control - Reprogram (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 8 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

FM	Flash Module
----	--------------