



NUMBER: 18-032-16 REV. A

GROUP: Vehicle Performance

DATE: August 16, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-032-16, DATED MARCH 30, 2016, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE ADDITIONAL SYMPTOM/CONDITIONS AND A LOP.**

FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: Powertrain Diagnostic And System Improvements

OVERVIEW:

This bulletin involves reprogramming of the Powertrain Control Module (PCM) with the latest software.

MODELS:

2016	(LA)	Dodge Challenger
2016	(LD)	Dodge Charger

**NOTE: This bulletin applies to vehicles within the following markets/countries:
NAFTA, LATAM, EMEA and APAC.**

NOTE: This bulletin applies to vehicles built on or before August 05, 2016 (MDH 0805XX) equipped with a 6.2L V8 Supercharged Engine (Sales Code ESD).

SYMPTOM/CONDITION:

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find that the following Diagnostic Trouble Codes (DTCs) have been set:

- ****U1424** - Implausible Engine Torque Signal Received.
- P0122 - Throttle Position Sensor 1 Circuit Low.
- P0123 - Throttle Position Sensor 1 Circuit High.

- P0222 - Throttle Position Sensor 2 Circuit Low.
- P0223 - Throttle Position Sensor 2 Circuit High.
- P2299 - Brake Pedal Position/Accelerator Pedal Position Incompatible.
- P2227 - Barometric Pressure Circuit Performance.
- P3032 - Barometric Pressure Sensor Performance Plausibility.
- P0441 - EVAP Purge System Performance.
- P0455 - EVAP System Large Leak.
- P0335 - Crankshaft Position Sensor Circuit.**
- P0339 - Crankshaft Position Sensor Intermittent.
- P0456 - EVAP System Small Leak.

**In addition, the following software enhancement is available:

- Changes to Enhanced Automated Oil Change Indicator (EAOCI) calibration to more accurately determine maintenance interval based on engine loads and driving habits.**

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above or if the technician finds the DTCs, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-06-MM	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1 - Engine Repair and Performance	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 5 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use. If the customer came in with an issue and if the dealer finds a software update to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash