



NUMBER: 08-058-21

GROUP: 08 - Electrical

DATE: April 15, 2021

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Flash: Integrated Dual Charging Module (IDCM) Updates

OVERVIEW:

This bulletin involves reprogramming the IDCM with the latest available software.

MODELS:

2020 - 2021 (BV) Jeep Renegade

NOTE: This bulletin applies to vehicles within the following markets/countries: EMEA.

NOTE: This bulletin applies to vehicles built on or before March 10, 2021 (MDH 0310XX) equipped with 1.3L I4 Turbo PHEV Engine (Sales Code EYG).

SYMPTOM/CONDITION:

Customers may notice the following:

- B22A9-17 - ECU Internal Performance-Circuit Voltage Above Threshold.
- P0D2A-00 - Battery Charger 1 Input Current Too High.
- P0CF3-00 - Control Pilot Circuit Open.
- P0CF4-00 - Control Pilot Circuit Performance.
- B22A9-87 - ECU Internal Performance-Missing Message.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic trouble Codes (DTCs) or symptom conditions, other than the ones listed are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/conditions listed above or if the technician finds the DTCs, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the IDCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-92-02	Module, Integrated Dual Charging (IDCM) - Reprogram (0 - Introduction)	6 - Electrical And Body Systems	0.7 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 4 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must use failure code CC with this Service Bulletin.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Service Bulletin flash/reprogramming conditions.

CC	Customer Concern
----	------------------