

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: CHECK ENGINE LIGHT ON WITH DTC P061B:00 IN HIGH TEMPERATURES AT HIGH ELEVATIONS	Bulletin No.: 01-021/18
	Last Issued: 10/22/2018

APPLICABLE MODEL(S)/VINS

2013 CX-5 vehicles with A/T without kickdown switch with VINs lower than JM3KE*****148075 (produced before September 6, 2012)

2013-2015 CX-5 vehicles with M/T with VINs lower than JM3KE*****552473 (produced before November 12, 2014)

2016 CX-5 with VINs lower than JM3KE*****921726 (produced before December 21, 2016)

2017-2018 CX-5 vehicles with VINs lower than JM3KF*****443351 (produced before July 2, 2018)

Mexico spec:

2013 CX-5 with VINs lower than JM3KE*****170454 (produced before February 28, 2013)

2016-2017 CX-5 with VINs lower than JM3KE*****921716 (produced before December 21, 2016)

2018 CX-5 vehicles with VINs lower than JM3KF*****443351 (produced before July 2, 2018)

DESCRIPTION

Some vehicles may experience a lack of power and the check engine light on with DTC P61B:00 stored in the PCM memory when driving in high temperatures at high elevations.

- DTC P061B:00 - [PCM] Internal control module torque calculation performance problem

This concern may be caused by improper PCM control logic. The engine torque calculation error may increase in high temperatures at high elevations. To eliminate this concern, the PCM software has been modified.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

PCM REPROGRAMMING:

1. Verify the customer concern.
2. Reboot the IDS to clear memory before reprogramming.
3. Using IDS **111.03** or later software, reprogram the PCM to the latest calibration (refer to "Calibration Information" table) by following the "Module Reprogramming" procedure.

NOTE:

Page 1 of 6

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

- Always update the IDS tool first, then follow on-screen instructions to download the needed calibration file for PCM reprogramming.
 - It is not necessary to remove any fuses or relays during PCM reprogramming when the IDS screen prompts you to do so. You may accidentally stop power to one of the PCM terminals and cause the PCM to be blanked, or you may receive error messages during the IDS reprogramming procedure.
 - IDS shows the calibration part numbers after programming the PCM.
 - Please be aware that PCM calibration part numbers and file names listed in any Service Bulletin may change due to future releases of IDS software, and additional revisions made to those calibrations for service related concerns.
 - When reprogramming a PCM, IDS will always display the “latest” calibration P/N available for that vehicle. If any calibration has been revised/updated to contain new information for a new service concern/issue, it will also contain all previously released calibrations.
 - Start/Stop button vehicles only: DO NOT press the start/stop button during the reprogramming process.
 - When performing this procedure, we recommend using the “Power Supply” mode in the Battery Management System to keep the vehicle battery up to capacity. If a different charger is used, make sure it does not exceed 20 AMPS. If it exceeds 20 AMPS, it could damage the VCM.
4. After performing the PCM reprogramming procedure, clear DTCs.
 5. After clearing DTCs, start the engine and confirm that no warning lights stay on.
 6. Record customer presets in the infotainment system.
 7. Disconnect the negative battery cable and wait for 30 seconds or more to reset the fuel control learning data.
 8. Re-connect the negative battery cable.
 9. Re-enter customer presets in infotainment system.

NOTE:

If any DTCs should remain after performing DTC erase, diagnose the DTCs using MGSS online instructions and submit a warranty claim according to the normal warranty procedure.

CALIBRATION INFORMATION**NOTE:**

- If the calibration file is with the suffix in the table or later, the PCM already has the modified calibration.
- Older File Name column shows the first four letters of the older file name only if some of the older file names are different from the new file name.

2013-2015 CX-5:

Engine	Emission	Transmission	Drive	File Name	Older File Name	Note
2.0L	Calif	M/T	2WD	PUZ2-188K2-E	PE01	Mitsubishi
				PUZ4-188K2-E	PE1G	Denso
	Fed	M/T	2WD	PUZ3-188K2-E	PE1C	Mitsubishi
				PUZ5-188K2-E	PE1L	Denso

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by “do-it-yourselfers.” Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

2013 CX-5 (without kickdown switch):

Engine	Emission	Transmission	Drive	File Name	Note
2.0L	Calif	A/T	2WD	PE02-188K2-T	Mitsubishi
				PE1H-188K2-S	Denso
			4WD	PE1B-188K2-T	Mitsubishi
				PE1K-188K2-S	Denso
			Fed	A/T	2WD
			PE1M-188K2-S		Denso
		4WD	PE1F-188K2-T		Mitsubishi
			PE1P-188K2-S		Denso

2016 CX-5:

Engine	Emission	Transmission	Drive	File Name	Note
2.0L	Calif	M/T	2WD	PS32-188K2-E	Mitsubishi
				A/T	
		PS33-188K2-E	Mitsubishi		
				PS40-188K2-E	Denso
				4WD	PS34-188K2-E
			4WD	PS41-188K2-E	Denso
				Fed	M/T
		A/T	2WD	PS42-188K2-E	
				A/T	2WD
		PS43-188K2-E	Denso		
		4WD	PS37-188K2-E		Mitsubishi
		PS44-188K2-E	Denso		
	2.5L	Calif	A/T	2WD	PYAJ-188K2-F
				PYAR-188K2-F	Denso
			4WD	PYAK-188K2-E	Mitsubishi

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

				PYAS-188K2-E	Denso
	Fed	A/T	2WD	PYAL-188K2-E	Mitsubishi
				PYAT-188K2-E	Denso
			4WD	PYAM-188K2-F	Mitsubishi
				PYAV-188K2-F	Denso

2017-2018 CX-5:

Engine	Emission	Transmission	Drive	File Name	Note
2.0L	Calif/Fed	M/T	2WD	PSJB-188K2-F	Mitsubishi
				PSJC-188K2-F	Denso
2.5L	Calif	A/T	2WD	PYMX-188K2-G	Mitsubishi
				PYNA-188K2-G	Denso
			4WD	PYNB-188K2-G	Mitsubishi
				PYNC-188K2-G	Denso
	Fed	A/T	2WD	PYND-188K2-G	Mitsubishi
				PYNE-188K2-G	Denso
			4WD	PYNF-188K2-G	Mitsubishi
				PYNG-188K2-G	Denso

NOTE: 2018 CX-5 2.5L is only applicable for Canada.

2013 CX-5 (Mexico Spec. without kickdown switch):

Engine	Transmission	Drive	File Name	Note
2.0L	A/T	2WD	PE2P-188K2-M	Mitsubishi
			PE2T-188K2-L	Denso
		4WD	PE2R-188K2-M	Mitsubishi
			PE2V-188K2-L	Denso

2016-2017 CX-5 (Mexico Spec.):

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Engine	Transmission	Drive	File Name	Note
2.0L	A/T	2WD	PS38-188K2-E	Mitsubishi
			PS45-188K2-E	Denso
2.5L	A/T	2WD	PYAN-188K2-D	Mitsubishi
			PYAW-188K2-D	Denso
		4WD	PYAP-188K2-D	Mitsubishi
			PYAX-188K2-D	Denso

2018 CX-5 (Mexico Spec.):

Engine	Transmission	Drive	File Name	Note
2.0L	A/T	2WD	PSJD-188K2-E	Mitsubishi
			PSJE-188K2-E	Denso
2.5L	A/T	2WD	PYNH-188K2-E	Mitsubishi
			PYNJ-188K2-E	Denso
		4WD	PYNK-188K2-E	Mitsubishi
			PYNL-188K2-E	Denso

NOTE: It is not necessary to order a PCM part for this repair procedure.

WARRANTY INFORMATION**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Fed. Emission Warranty (long term).
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	6X
Damage Code	9W
Part Number Main Cause	5555 RP PCM
Quantity	0

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Bulletin No.: 01-021/18	Last Issued: 10/22/2018
--------------------------------	--------------------------------

Operation Number / Labor Hours:	XXP7XXFX / 0.3 Hrs.
---------------------------------	---------------------

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.