



Preliminary Information

PIP5568C Service Engine Soon Light Comes on With All 4 Camshaft Position System Performance DTCs P0011 P0014 P0021 and P0024 Setting.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018 - 2019	All	All	3.6 LFY	All
Buick	LaCrosse	2017 - 2019	All	All	3.6 LGX	All
Buick	Regal	2018 - 2019	All	All	3.6 LGX	All
Cadillac	ATS	2016 - 2019	All	All	3.6 LGX	All
Cadillac	CT6	2016 - 2019	All	All	3.0 LGW, 3.6 LGX	All
Cadillac	CTS	2016 - 2019	All	All	3.6 LGX	All
Cadillac	XT5	2017 - 2019	All	All	3.6 LGX	All
Chevrolet	Traverse	2018 - 2019	All	All	3.6 LFY	All

Involved Region or Country	North America
Condition	Some customers may come in with a MIL/SES illuminated after an auto stop and restart event, drivability concerns may be possible when these codes set.
Cause	Tech will find a) All 4 phaser performance DTCs are set (P0011 AND P0021 AND P0014 AND P0024) or b) Pairs of phaser performance DTCs are set (P0011 AND P0021 OR P0014 AND P0024) or c) In some cases, single and triple phaser performance DTCs are set (less likely) (P0011 first and P0021 AND P0014 AND P0024)

Correction:

Clear the codes and return the vehicle to the customer.
At this time the cause for this concern is under investigation.
Please do not replace any parts for the concern at this time.

NOTE: We will update the PI or create a bulletin to replace this PI when more information becomes available.

Version History

Version	4
Modified	05/7/2018 - Created. 06/26/2018 - Updated Correction Section. 07/25/2018 - Updated to include 2019 MY. 11/13/2018 - Updated concern information.



© 2018 General Motors. All Rights Reserved.