



JTB00659NAS3

TECHNICAL BULLETIN

08 FEB 2019

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in blue

SECTION:

303-14

SUBJECT/CONCERN:

Engine MIL Illuminated With DTC P0191-85 Stored

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
E-PACE (X540)	2018	Z00291-Z31920	Graz (Austria)	INGENIUM I4 2.0L Petrol

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
F-PACE (X761)	2018	249771-351697	Solihull	INGENIUM I4 2.0L Petrol
XE (X760)	2018	P18140-P43066	Castle Bromwich	INGENIUM I4 2.0L Petrol

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

The engine MIL (Malfunction Indicator Lamp) may be illuminated with DTC (Diagnostic Trouble Code) P0191-85 stored in the Powertrain Control Module (PCM).

CAUSE:

This may be caused by an incorrect PCM calibration causing a false flag of the DTC.

ACTION:

Should a customer express this concern, follow the Diagnostic Procedure below.

PARTS:

No Parts Required

TOOLS:



Jaguar Land Rover-approved
Midtronics battery
power supply



Jaguar Land Rover-approved
diagnostic
equipment with
latest PATHFINDER
software

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.
- The JLR claims submission system requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Powertrain Control Module (PCM) - Update ECU	86.98.60	0.2	04	AJ813994

NOTE:

Normal Warranty procedures apply.

DIAGNOSTIC PROCEDURE:

CAUTIONS:

- A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle startup battery.

- All ignition ON/OFF requests **MUST** be performed; failure to do these steps may cause damage to vehicle control modules.

 NOTE:

Use the Jaguar Land Rover claims submission system for Field Service Action program eligibility requiring a Powertrain Control Module (PCM) software update. If eligible, perform and claim the update as per that program using the latest PATHFINDER software.

- 1 Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle startup battery.

2

 NOTE:

The Jaguar Land Rover-approved diagnostic equipment must be loaded with PATHFINDER version 211 (or later).

Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.

3

 NOTE:

The Jaguar Land Rover-approved diagnostic equipment will read the correct Vehicle Identification Number (VIN) for the current vehicle and automatically take the vehicle out of Transit mode (if required).

Follow all on-screen instructions.

4

Select **ECU Diagnostics**.

5

Select **Powertrain Control Module (PCM)**.

6

Select **Update ECU**.

- 1 Follow the on-screen instructions until the application finishes successfully.

7 Select **ECU Functions**.

8 Select **Powertrain control module adaption clear**.

- 1 Follow the on-screen instructions until the application finishes successfully.
-

9 Exit the current session.

- 1 If required, reset the vehicle to **Transit mode**.
 - 2 Select the **Exit** icon.
-

10 Disconnect the diagnostic equipment and battery power supply from the vehicle.