



Technical Service Bulletin

01 MIL on, DTC P24CC00 and/or P24CB00 stored in the ECM

01 19 14 2051053/4 March 26, 2019. Supersedes Technical Service Bulletin Group 01 number 19-11 dated March 15, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2013 - 2015	All	TDI

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised Warranty (Added Claim Type)
3	03/15/2019	Revised <i>Required Parts and Tools</i> (Added AdBlue)
2	06/12/2018	Revised header data (Removed VIN break)

Customer states:

- MIL on.

Workshop findings:

One or more of the following DTCs is stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P24CC00** (Reductant Tank Cap Switch Circuit Range Open).
- **DTC P24CB00** (Reductant Tank Cap Switch Circuit).

No relevant component or electrical problems are found when Guided Fault Finding (GFF) is run on the stored fault codes.

Technical Background

The reducing agent active tank cap switch is prone to sticking, especially in hot and humid climates. If the switch sticks when the vehicle is refilled with AdBlue, this fault will be triggered.

Production Solution

The vehicle is out of production, improved part as a service solution.



Technical Service Bulletin

Service

1. Remove active tank according to instructions in the Elsa Repair Manual.
2. Replace cap microswitch located on active tank filler neck with improved part 4L0133093B. Reinstall active tank according to instructions in the Elsa Repair Manual.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • G14 - Verify Coverage in ElsaPro. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2681		
Damage Code:	0050		
Labor Operations:	Reductive agent container remove + reinstall	2681 1900	See SRT
	Reductive agent inspected + added	2688 3500	See SRT
	Replace active tank cap switch	2681 1999	20 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 20 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2051053/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
4L0133093B	Active tank cap switch	01
GUS052910A3	AdBlue	As needed (Max 2.3)
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA

Additional Information

All parts and service references provided in this TSB (2051053) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.