



Technical Service Bulletin

20 MIL on, DTC P046100 stored in the ECM

20 19 11 2043357/10 January 29, 2019. Supersedes Technical Service Bulletin Group 20 number 18-08 dated October 1, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2015 - 2016	All	Not Applicable
A4, A5, A5 Cabriolet, and Q5	2013 - 2016	All	2.0 TFSI
Q5	2013 – 2016	All	Hybrid
A8	2015 - 2017	All	3.0 TFSI
A6, A7	2014 – 2015	All	3.0 TFSI
Q5, SQ5	2014 – 2015	All	3.0 TFSI
S4, S5, and S5 Cabriolet	2014 – 2015	All	3.0 TFSI
S8	2013 - 2017	All	4.0 TFSI
RS 7	2014 - 2016	All	4.0 TFSI
S6, S7	2013 - 2016	All	4.0 TFSI
RS 5, RS 5 Cabriolet	2013 - 2015	All	4.2 TFSI
A8	2013 - 2017	All	4.0 TFSI

Condition

REVISION HISTORY		
Revision	Date	Purpose
10	-	Revised header (Added model) Revised <i>Service</i> (Updated table)
9	10/01/2018	Revised title Revised <i>Condition</i> (Added Note)
8	07/31/2017	Revised header data (Added model years)

Customer states:



Technical Service Bulletin

- MIL on.

Workshop findings:

The following DTC may be present in the engine control module (ECM), J623 (address word 0001):

- **DTC P046100** (Fuel level sensor, circuit range/performance).



Note:

If **campaign 19N4** has been performed, do not perform this TSB at this time! 19N4 will be updated in the future to deal with P046100 again. In the meantime, customers should be advised to fill their tank with the ignition off to prevent DTC P046100 from occurring.

All 2.0L ECM variants listed in this TSB are affected, except the below two:

- 8R1907115P.
- 8R1907115M.

Technical Background

DTC P046100 can be caused by miscalculations within the ECM software when the vehicle is being filled with gasoline while the ignition is on.

Production Solution

New ECM software implemented to correct the condition.

Service



Note:

Check the vehicle ECM software part number/version prior to the SVM update.

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the ECM, J623 (address word 0001) using the SVM action code as listed in the table below.
3. After SVM update, cycle the ignition.
4. Start the engine. If engine runs rough and then surges, cycle the ignition once again.
5. Reset TPMS.



Technical Service Bulletin

Model	Engine	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version	SVM Code Input
A3	2.0 TFSI	5G0906259A	<0006	5G0906259A	0006	01A203
A3	1.8 TFSI	8V0906264A	0001	8V0906264D	0004	01A203
A3	1.8 TFSI	8V0906264D	< 0004	8V0906264D	0004	01A203
S3	2.0 TFSI	8V0906259B	Any	8V0906259H	0001	01A203
S3	2.0 TFSI	8V0906259E	Any	8V0906259H	0001	01A203
A4, A5, and A5 Cabriolet	2.0 TFSI	8K5907115N	0001, 0002, or 0003	8K5907115N	0004	01A203
A4, A5, and A5 Cabriolet	2.0 TFSI	8K5907115J	0001 or 0002	8K5907115N	0004	01A203
A4, A5, and A5 Cabriolet	2.0 TFSI	8K5907115P	0001	8K5907115P	0002	01A203
A4, A5, and A5 Cabriolet	2.0 TFSI	8K5907115M	0001, 0002, or 0003	8K5907115M	0004	01A203
A4, A5, and A5 Cabriolet	2.0 TFSI	8K5907115Q	0001	8K5907115Q	0002	01A203
Q5	2.0 TFSI	8R1907115N	0001	8R1907115N	0002	01A203
Q5	2.0 TFSI	8R1907115P	0001	8R1907115P	0002	01A203
Q5	2.0 TFSI H	8R1907115L	0001, 0002, or 0003	8R1907115L	0004	01A203
Q5	2.0 TFSI H	8R1907115M	0001 or 0002	8R1907115M	0003	01A203
Q5	2.0 TFSI	8R1907115F	0001	8R1907115L	0004	01A203
S4, S5, and S5 Cabriolet	3.0 TFSI	8K5907551G	0001, 0002, 0003, 0004, or 0005	8K5907551G	0006	01A203
S5	4.2 TFSI	8T2907560F	0002, 0003, or 0004	8T2907560F	0005	01A203



Technical Service Bulletin

RS5 and RS5 Cabriolet	4.2 TFSI	8T2907560F	0002, 0003, or 0004	8T2907560F	0005	01A150
Q5	3.0 TFSI	8R0907551F	0001, 0002, 0003, 0004, or 0005	8R0907551F	0006	01A203
SQ5	3.0 TFSI	8R0907551G	0001, 0002, 0003, 0004, or 0005	8R0907551G	0006	01A203
A8	3.0 TFSI	4H2907551A	0001, 0003, or 0004	4H2907551A	0008	01A203
A6, A7	3.0 TFSI	4G0907551J	0001, 0002, or 0003	4G0907551J	0004	02A210
S6, S7	4.0 TFSI CEUC	4G0906014	0011	4G0906014	0012	01A203
S6, S7	4.0 TFSI CEUC	4G0906014A	0007	4G0906014A	0008	01A203
S6, S7	4.0 TFSI CEUC	4G0906014B	0008	4G0906014B	0009	01A203
S6, S7	4.0 TFSI CEUC	4G0906014E	0005	4G0906014E	0006	01A203
S6, S7	4.0 TFSI CTGE	4G0906014C	0005	4G0906014C	0006	01A203
S6, S7	4.0 TFSI CTGE	4G0906014D	0001	4G0906014D	0002	01A203
RS7	4.0 TFSI CRDB	4G0906560A	0005	4G0906560A	0006	01A203
RS7	4.0 TFSI CRDB	4G0906560	0011	4G0906560	0012	01A203
RS7	4.0 TFSI CRDB	4G0906560B	0007	4G0906560B	0008	01A203
RS7	4.0 TFSI CWUB	4G0906560D	0001	4G0906560G	0002	01A203



Technical Service Bulletin

RS7	4.0 TFSI CWUB	4G0906560F	0002	4G0906560F	0003	01A203
RS7	4.0 TFSI CWUB	4G0906560G	0001	4G0906560G	0002	01A203
RS7 Performance	4.0 TFSI CWUC	4G0906560G	0001	4G0906560G	0002	01A203
A8	4.0 TFSI CEUA	4H0906014	0007	4H0906014	0008	01A203
A8	4.0 TFSI CEUA	4H0906014A	0005	4H0906014A	0006	01A203
A8	4.0 TFSI CEUA	4H0906014B	0004	4H0906014B	0005	01A203
A8	4.0 TFSI CEUA	4H0906014C	0004	4H0906014C	0005	01A203
A8	4.0 TFSI CEUA	4H0906014D	0004	4H0906014D	0005	01A203
A8	4.0 TFSI CEUA	4H0906014H	0005	4H0906014H	0006	01A203
A8	4.0 TFSI CEUA	4H0906014L	0004	4H0906014L	0005	01A203
A8	4.0 TFSI CTGA	4H0906014G	0007	4H0906014G	0008	01A203
A8	4.0 TFSI CTGA	4H0906014J	0005	4H0906014J	0006	01A203
A8	4.0 TFSI CTGA	4H0906014K	0004	4H0906014K	0005	01A203
A8 S	4.0 TFSI CTGF	4H0906014N	0001	4H0906014N	0002	01A203
S8	4.0 TFSI CGTA	4H0907557	0009	4H0907557	0010	01A203
S8	4.0 TFSI CGTA	4H0907557A	0005	4H0907557A	0006	01A203



Technical Service Bulletin

S8	4.0 TFSI CGTA	4H0907557B	0004	4H0907557E	0004	01A203
S8	4.0 TFSI CTFA	4H0907557E	0003	4H0907557E	0004	01A203
S8	4.0 TFSI CTFA	4H0907557C	0005	4H0907557C	0006	01A203
S8	4.0 TFSI CTFA	4H0907557D	0005	4H0907557D	0006	01A203
S8	4.0 TFSI CTFA	4H0907557F	0002	4H0907557F	0003	01A203
S8 +	4.0 TFSI DDTA	4H0907557G	0003	4H0907557G	0004	01A203
S8 +	4.0 TFSI DDTA	4H0907557H	0001	4H0907557H	0002	01A203

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • 1E1 up to 8 Years/80,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	Check software level in ECM (with no update needed)	2470 0199	Max 10 TU
Diagnostic Time:	GFF –Perform update through GFF and clear faults	0150 0000	Time stated on diagnostic protocol (Max 50 TU)
	Road test before service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU



Technical Service Bulletin

Claim Comment:	As per TSB #2043357/10
-----------------------	------------------------

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions*.

All part and service references provided in this TSB (2043357) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.