



Technical Service Bulletin

91 SOS warning displayed in instrument cluster, DTC B191604 stored in the gateway control module

91 19 33 2051664/2 February 5, 2019. Supersedes Technical Service Bulletin Group 91 number 18-02 dated June 26, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, Q5, and Q7	2018	All	With connected gateway

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised title Revised header (Remove MY2019) Revised <i>Production Solution</i> (Updated information) Revised <i>Warranty</i> (Updated Labor Operations)
1	06/26/2018	Initial publication

Customer states:

- A warning message appears on the instrument cluster. The message reads "Emergency call function: malfunction! Restricted functionality. Please contact Service" (Figure 1).



Figure 1. Warning message shown in instrument cluster.

Workshop findings:

The following DTC may be stored in the gateway control module, J533 (address word 0019) as static or intermittent:

- DTC B191604** (Backup battery Faulty).



Technical Service Bulletin

Technical Background

Incorrect software parameter for the connected Gateway's back-up battery charge monitoring. The system must be reset by performing a manual discharge of the connected Gateway's backup-battery.

Production Solution

The part is no longer used in production.

Service

1. Perform a manual discharge of the connected gateway's back-up battery by removing constant power (KL30) and accessory power (KL15), while KL15 is switched on.

This will force the connected gateway to draw power from the backup battery, lowering the voltage of the back-up battery.

Several discharge cycles maybe needed for the voltage of back-up battery to fall within the specified parameters.



Note:

The steps for the manual discharge, 4 through 8, are to be performed with the Engine OFF, and without a 12V charger on the vehicle.

2. Gain access to fuse panel SB, located behind the driver's side footwell cover. Consult the repair manual for instructions on accessing fuse panel SB.
3. Locate the two fuses which supply constant power (KL30) and accessory power (KL15) to the connected gateway. Consult the wiring diagram, or owner's manual for fuse location and size.
4. Ensure that accessory power (KL15) is ON.
5. Remove the two fuses identified in Step 3.
6. Wait 30 seconds with both fuses removed.
7. Reinstall the two fuses.
8. Turn off accessory power (KL15).
9. Repeat steps 4 through 8 **six** additional times. This will result in a total of seven discharge cycles.
10. Following seven discharge cycles, clear the fault memory of the connected gateway module:
 - In ODIS GFF, recheck the fault memory of the connected gateway.



Technical Service Bulletin

- The fault should now be static and should not return after clearing the fault memory.

In the event that fault does not clear, and is marked as Active, then replace the connected gateway's backup battery. Consult the repair manual for instructions on replacing the connected gateway's backup battery. Consult the parts catalog for the correct part number of the connected gateway's backup battery.

Connected Gateway Fuse Location Table Reference:						
KL30				KL15		
Model	Fuse Number	Panel	Location	Fuse Number	Panel	Location
Q7	SB7	ST5	Figure 2.2	SB2	ST4	Figure 2.1
Q5	SB7	ST2	Figure 3.1	SB2	ST4	Figure 3.2
A4	SB7	ST2	Figure 3.1	SB2	ST4	Figure 3.2
A5	SB7	ST2	Figure 3.1	SB2	ST4	Figure 3.2




Figure 2. Q7 Driver's Side Footwell Fuse Box. 1: KL15 Fuse. 2: KL30 Fuse.



Technical Service Bulletin




Figure 3. A4, A5, and Q5 Driver's Side Footwell Fuse Box. 1: KL30 Fuse. 2: KL15 Fuse.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9035		
Damage Code:	0039		
Labor Operations:	All models:		
	Check back-up battery for telematics	9178 0199	20 TU
	A4, A5, and Q7:		
	A-pillar trim remove + reinstall	7057 1905	See SRT
	Q5:		
	A-pillar trim remove + reinstall	7057 1905	See SRT
	As required only if battery is replaced:		
	A4, A5, and Q5:		



Technical Service Bulletin

	Telematics emergency battery replace	9178 5550	See SRT
	Q7:		
	Telematics emergency battery replace	9178 5550	See SRT
	Data bus control module remove + reinstall (Reduced due to overlap with A-pillar trim remove + reinstall)	9035 1999	30 TU
	Front seat remove + reinstall	7201 1900	See SRT
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	0150 0000	Time stated on diagnostic protocol (Max 100 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2051664/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Parts are only needed in the event that the fault does not clear.		
Part Number	Part Description	Quantity
4M0907486	Battery for emerg. operation	01 (As needed)
See ETKA	Fasteners, Bolts, Nuts and Screws as needed per the Repair Manual	See ETKA/ELSA

Additional Information

All parts and service references provided in this TSB (2051664) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any



Technical Service Bulletin

time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.