


LATEST VEHICLE CONCERN FIXES



DPF Efficiency Below Threshold	17-19MY RR, RRS, & All New Discovery 3.0L TDV6
<u>Customer Voice:</u> – Check Engine Light illuminated <u>Technical Description:</u> – P2002-00 for DPF Efficiency below threshold is stored in the PCM. This is usually not paired with any Red/Amber warnings for unsuccessful regeneration. <u>Status:</u> – Under Investigation – Leak check the system and address any leaks. Diagnose all related exhaust codes that could affect DPF efficiency based on TOPIx guidance. If diagnosis leads you to replacement of the DPF, hold onto the part and raise an EPQR. Engineering requires parts for analysis to progress the project.	 A technical diagram of the exhaust system for a 3.0L TDV6 engine. It shows the DPF (Diesel Particulate Filter) and various sensors and components. Labels include: SH270, SH241, H82, SH210, SH201C, HE1, SA282, SH221, SH201A, SA282, HE1, SA221, S439, H81, SH201B, and S286. The diagram is a 3D perspective view of the exhaust manifold, DPF, and tailpipe assembly.

