



NUMBER: 18-105-15

GROUP: Vehicle Performance

DATE: December 15, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: 1.4L Diagnostic And System Improvements

OVERVIEW:

This bulletin involves selectively erasing and reprogramming the Powertrain Control Module (PCM) with new software.

MODELS:

2016 (BF) Fiat 500L

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or before November 18, 2015 (MDH 1118XX) equipped with a 1.4L Engine (Sales Code EAM) with 6-speed aisin transmission (Sales Code DF4) or equipped with 6-speed C633 twin clutch (Sales Code DA1) or equipped with 6-speed C635 manual transmission (Sales Code DE1).

SYMPTOM/CONDITION:

A small number of customers may experience one of the following conditions or a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the Technician may find a Diagnostic Trouble Code has been set in the PCM:

- P0141 - O2 Sensor 1/2 Heater Performance.
- Crank no start condition in extreme cold temperatures of -4°F (-20°C) partially due to the available fuel blend conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all vehicle systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition or if the technician finds the DTC, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
2. Is vehicle equipped with a manual transmission?
 - a. Yes >>> P1302 - Transmission Self Learning will be present. **Depress clutch pedal fully to allow DTC to store**, proceed to [Step #3](#).
 - b. No >>> P1302 - Transmission Self Learning will be stored, proceed to [Step #3](#).
3. Perform Cruise Control Learn Procedure.
 - a. Turn the Ignition Key to the OFF/LOCK position for 10 seconds to allow the module to power down.
 - b. Turn the Ignition Key to the ON/RUN position.
 - c. Press, then release the Cruise ON/OFF button on the steering wheel.
 - d. Start the engine.
 - e. Press the Cruise ON/OFF button to verify that the Cruise indicator illuminates on the cluster.
4. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-06-GW	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	8 - Engine Performance	0.3 Hrs

NOTE: The expected completion time for the flash download portion of this procedure is approximately 4 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use. If the customer came in with an issue and the dealer found updated software to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash