



NUMBER: 18-006-15 REV. H

GROUP: Vehicle Performance

DATE: December 18, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-006-15 REV. G DATED OCTOBER 24, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS AND INCLUDES UPDATED BUILD DATES, SYMPTOM/CONDITION, SALES CODE, AND LABOR OPERATION.**

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-012. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING "HELP" THEN "HELP CONTENTS" AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: 2.4L Powertrain Diagnostic and System Improvements

OVERVIEW:

This bulletin involves reprogramming the Powertrain Control Module (PCM) with the latest available software.

MODELS:

2013 - 2015	(PF)	Dodge Dart
2015	(UF)	Chrysler 200

NOTE: **This bulletin applies to vehicles equipped with a 2.4L Engine (Sales Codes ED6 or ED8).**

SYMPTOM/CONDITION:

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination or one or more of the following conditions. Upon further investigation the technician may find the following Diagnostic Trouble Codes (DTCs) set in the PCM memory:

2015 UF Vehicles with (Sales Codes ED6, ED8)

- Improved vehicle acceleration.
- P0480 - Cooling Fan 1 Control Circuit/Open.
- P0456 - Evap System Small Leak.
- U0402 - Implausible Data Received From TCM.
- Engine Startup Flare and Idle Surge.
- P2172 - High Airflow/Vacuum Leak Detected.
- P1D73 - AGS Performance.
- U0140 - Lost Communication With Body Control Module.
- P0441 - Evap Purge System Performance.
- P0116 - Engine Coolant Temperature Sensor 1 Performance.
- P050D - Cold Start Rough Idle.

2015 PF Vehicles with (Sales Codes ED6, ED8)

- **P0133 - O2 Sensor 1/1 Slow Response.
- P0456 - Evap System Small Leak.**
- Low Idle Speed After Cold Start between 14°F to 32°F (-10°C to 0°C).
- Cold Idle Surge With AC Engaged.
- Improve cabin warm up in cold weather, when the vehicle is in park or neutral and the temperature is between 10°F to 40°F (-12°C to 4.5°C).
- P219A - Bank 1 Air-Fuel Ratio Imbalance.
- P2172 - High Airflow/Vacuum Leak Detected.
- P1D73 - AGS Performance.
- U0140 - Lost Communication With Body Control Module.
- P0116 - Engine Coolant Temperature Sensor 1 Performance.
- P050B - Cold Start Ignition Timing Performance.
- P050D - Cold Start Rough Idle.
- P061A - Level 2 Torque Performance.
- P2172 - High Airflow/Vacuum Leak Detected (Instantaneous Accumulation).

2013-2014 PF Vehicles **(Sales Codes ED6)

- P0456 - Evap System Small Leak.**
- P219A - Bank 1 Air-Fuel Ratio Imbalance.
- P2251 - O2 Sensor 1/1 Negative Current Control Circuit Open.
- P106A - Cylinder 3 Oil Supply Solenoid Valve Switch Off Time Out Of Range.
- P2172 - High Airflow/Vacuum Leak Detected.
- P1D73 - AGS Performance.
- U0140 - Lost Communication With Body Control Module.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all vehicle systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, or if the technician finds any of the DTCs listed above perform the Repair Procedure.

REPAIR PROCEDURE:

CAUTION: The Transmission Control Module (TCM) must be updated to the latest available software at the conclusion of this repair procedure. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the TCM software.

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.

NOTE: If the PCM already has the latest software, use inspection LOP 18-19-06-FA to close the active RRT.

2. Clear any DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allows them to be cleared.
3. Verify the TCM is programmed with the latest available software. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the TCM software.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-06-FA	Module, Powertrain Control (PCM) - Inspection Only (0 - Introduction)	8 - Engine Performance	0.2 Hrs
18-19-06-GV	Module, Powertrain Control (PCM) - Reprogram (0 - Low Skilled)	8 - Engine Performance	0.3 Hrs

NOTE: The expected completion time for the flash download portion of this procedure is approximately 6 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use. If the customer came in with an issue and the dealer found updated software to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash