



Preliminary Information

PIP5650A Diagnostic Tip: Possible DTC P3075 That May Be Set Current or History

[Proactive](#)
[Models](#)

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XT4	2019	All	All	2.0 LSY	All
Chevrolet	Silverado 1500 (New Model)	2019	All	All	2.7 L3B	All
GMC	Sierra 1500 (New Model)	2019	All	All	2.7 L3B	All

Involved Region or Country:	North America
Condition:	DTC P3075 that may be set current or in history.
Cause:	Possible cooling system low on coolant or air trapped in cooling system.

If you encounter a vehicle with the above condition complete the following steps. Do not replace the Coolant Pump assembly at this time.

Pressure test the cooling system to confirm no coolant leaks are present. Any leaks in the cooling system should be repaired using Service Information.

Once the coolant leak has been repaired, refer to the latest Cooling System Draining and Filling procedure in SI for coolant fill and bleeding procedures.

Note: Once the engine is started after the coolant service fill procedure, it will be possible that DTC P3075 may reset until all the air is properly purged from the cooling system. At this point any codes should be cleared, the engine should be at operating temperature and the vehicle road tested to completely purge any remaining air from the cooling system.

Once complete clear any DTC's and operate the vehicle under the conditions for running the trouble code per SI.

Note: The P3075 P3076 can detect coolant flow based failures.

The intrusive diagnostic test will run once per ignition cycle if all enable conditions are met per SI. The intrusive diagnostic will run the coolant pump at roughly 4000rpm for 15 seconds and evaluates the pump motor AC current to be within expected range.

The coolant pump AC current feedback will be lower if the cooling system is leaking or low on coolant.

Using GDS confirm the p3075 has ran and passed in the current drive cycle to ensure the diagnostic has executed and no fault is detected before releasing the vehicle back to the customer.

If the vehicle returns for a second time with DTC P3075 replace the Coolant Pump assembly. Parts will be returned to the Warranty Parts Center.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base W arranty coverage), use the following labor operation. Reference the Applicable W arranties section of Investigate V ehicle History (IVH) for coverage information.

Labor Operation:	Description	Labor Time:
4087038	Pressure test cooling system	0.3 hr.

Version History

Version	2
Modified	05/20/2019 - Created on 05/22/2019- Updated to add additional information for conditions for running DTC P3075

