



Technical Service Bulletin

96 Adaptive light, pre sense malfunction or unable to calibrate, DTC C12B3F0 is stored in the driver assist module

96 19 41 2054765/1 August 5, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Audi e-tron quattro	2019 - 2020	All	With multifunction camera

Condition

Customer states:

- An Audi adaptive light system error is displayed in the instrument cluster.

Or

- An Audi pre sense system error is displayed in the instrument cluster.

Workshop findings:

The following DTC may be stored in the control module for driver assist systems, J1121 (address word 00A5):

- **DTC C12B3F0** (front camera for driver assist systems, dynamic calibration limit exceeded) with the symptom code 221202.

Or

- The test program "00A5 front camera for driver assist systems -R242 calibration" breaks off with the error message "The calibration was incorrect. Installation position wrong".

Or

- The front camera for assistance systems -R242- has to be replaced because of another issue.

Technical Background

Not applicable.

Production Solution

Not applicable.



Technical Service Bulletin

Service

1. Check whether an aluminum adhesive foil (part number **4K0 907 231 MTR**) with the dimensions 17mm x 7mm x 0.35 mm (length x width x height) is affixed to the front camera for assistance systems - R242- (Figure 1). It is needed to secure the front camera for assistance systems - R242- in the bracket.



Figure 1. How to correctly attach the aluminum adhesive foil on the front camera for assistance systems -R242-.



Technical Service Bulletin

2. Install the aluminum spacer if it was missing or a spacer with other dimensions is fitted. Remove the old spacer and the adhesive residue from the front camera for assistance systems - R242- (Figure 2).

Be careful to prevent damage to the front camera for assistance systems -R242- when removing the adhesive residue.



Figure 2. Incorrect attachment of spacer.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9638		
Damage Code:	0010		
Labor Operations:	Remove and install the camera for assistance systems	9638 1900	See SRT
	Modify camera for assistance systems	9638 4999	10 TU



Technical Service Bulletin

Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 75 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2054765/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
4K0907231MTR	Aluminum Foil Tape	01

Additional Information

All parts and service references provided in this TSB (2054765) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.