

ABS Brake Warning Light On and/or Trac Warning Light On

Service Category Brake

Section Brake Control/Dynamic Control System

Market USA

Lexus Supports
ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2013 - 2015	ES300H	

Introduction

Some 2013 – 2015 model year ES300h vehicles may exhibit a condition where the brake, ABS, and/or TRAC warning lights are on and/or a Check VSC message displays. One or more of the following Diagnostic Trouble Codes (DTCs) C1391, C1252, C1256, or C1253 will be stored in the vehicle's memory to be used as verification. This condition may be caused by a small internal brake fluid leak in the brake booster assembly with master cylinder. Follow the Repair Procedure in this bulletin to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
BR1909	R & R Brake Booster Assembly With Master Cylinder and R & R Brake Booster Pump Assembly	3.5	47050-33100	8C	99

APPLICABLE WARRANTY

- This repair is covered under the Lexus Basic Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

ABS Brake Warning Light On and/or Trac Warning Light On

Parts Information

PART NUMBER		PART NAME	QTY
PREVIOUS	NEW		
47050-33100	04009-05433	Brake Booster Assy W/Master Cylinder	1
47070-33020	04008-54833	Pump Assy, Brake Booster	1

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream ADVi*	ADE	TSADVUNIT	1
Techstream 2.0		TS2UNIT	
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

*Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 14.20.019 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

REQUIRED TOOLS & MATERIAL	FLUID TYPE	QUANTITY
Brake Fluid	DOT3 Brake Fluid	1 – 2 liters

Repair Procedure

1. Confirm the condition exists.
Are the brake, ABS, and/or TRAC warning lights ON and/or does a Check VSC message display?
 - **YES** — Continue to step 2.
 - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
2. Using Techstream, check for and record ANY stored DTCs.
Are ANY of the following DTCs stored: C1391, C1252, C1256, or C1253?
 - **YES** — Continue to step 3.
 - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

ABS Brake Warning Light On and/or Trac Warning Light On

Repair Procedure (continued)

3. Remove the brake booster assembly with master cylinder.
Refer to TIS, applicable model and model year Repair Manual:
 - [2013](#) / [2014](#) / [2015](#) ES300h:
Brake – Brake System – “Brake System (Other): Brake Booster: Removal”
4. Remove the brake booster pump assembly.
Refer to TIS, applicable model and model year Repair Manual:
 - [2013](#) / [2014](#) / [2015](#) ES300h:
Brake – Brake System – “Brake System (Other): Brake Booster Pump: Removal”
5. Install the NEW brake booster assembly with master cylinder.
Refer to TIS, applicable model and model year Repair Manual:
 - [2013](#) / [2014](#) / [2015](#) ES300h:
Brake – Brake System – “Brake System (Other): Brake Booster: Installation”
6. Install the NEW brake booster pump assembly.
Refer to TIS, applicable model and model year Repair Manual:
 - [2013](#) / [2014](#) / [2015](#) ES300h:
Brake – Brake System – “Brake System (Other): Brake Booster Pump: Installation”
7. Test-drive the vehicle to confirm the repair.