



Technical Service Bulletin

01 DTC(s) P195000, P10EF00, and/or B10F000 stored in engine control module or heating/air conditioning electronics

01 18 76 2047707/6 June 12, 2018. Supersedes Technical Service Bulletin Group 01 number 18-51 dated January 26, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2017 - 2018	All	Not Applicable
S4, S5, and SQ5	2018	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised header data (Added models)
5	01/26/2018	Revised <i>Service</i> (Added SVM table) Revised <i>Warranty</i> (Updated Labor Operations) Revised <i>Additional Information</i> (Updated disclaimer)
4	10/20/2017	Revised title (Added DTCs) Revised <i>Condition</i> (Updated concern and added Note) Revised <i>Technical Background</i> (Updated cause) Revised <i>Service</i> (Updated procedure) Revised <i>Warranty</i> (Added table) Revised <i>Required Parts and Tools</i> (Added table)

Customer states:

- The air conditioning system sometimes does not work, only warm air comes out of the vents
- The MIL is sometimes on in connection with poor engine performance

Workshop findings:

One or more of the following DTC(s) can be entered into the engine control module (ECM), J623 (address word 0001):

- **DTC P195000** (cooling fan -V7 - stiff/blocked)

And/or

- **DTC P10EF00** (restricted function because of radiator fan failure)



Technical Service Bulletin

And/or the following DTC can be stored in the heating/air conditioning electronics, E87 (address word 0008):

- **DTC B10F000** (restricted function because A/C compressor was switched off by engine)



Note:

After terminal 15 cycle/ignition cycle the air conditioning works again and the engine emergency operation ends.



Tip: This DTC has no effect on the function of the cooling fan and does not indicate a failure in the cooling fan.

Technical Background

Voltage drop at hot start causes a DTC(s) to appear without cause.

Production Solution

Not applicable.

Service

Vehicles with 2.0 TFSI engine:

If this DTC is discovered during service or any other unrelated repair, erase the DTC upon exiting GFF.

When diagnosing this DTC due to a customer concern, only replace the cooling fan if the GFF test result instructs to replace the cooling fan.

Vehicles with 3.0 TFSI engine:

- Update the engine control module (ECM), J623 (address word 0001) using the SVM action code as listed in the table below, if necessary (see TSB 2011732: *00 Software Version Management (SVM), operating instructions*):

Model	Engine and/or Transmission	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
S4/S5 (all)	CWGD	8W0907559H	< 0008	8W0907559H	0008	01A234
SQ5	CWGD	80A907559C	< 0007	80A907559C	0007	01A234



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1908		
Damage Code:	0040		
Labor Operations:	3.0T engine only:		
	Connect battery charger and perform software update with SVM	2470 2599	50 TU
Diagnostic Time:	GFF - (2.0TFSI and 3.0T)	0150 0000	Time stated on diagnostic protocol (Max 20 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2047707/6		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions*.

All parts and service references provided in this TSB (2047707) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.