



Technical Service Bulletin

01 MIL on, DTC P045600 stored in the ECM; small EVAP leak

01 18 69 2044156/4 May 10, 2018. Supersedes Technical Service Bulletin Group 01 number 16-74 dated August 18, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2016	000001 - 111348	3.0 TFSI

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised title Revised <i>Warranty</i> (Added Labor Operation)
3	08/18/2016	Revised <i>Warranty</i> (Updated Damage Code)
2	08/10/2016	Revised <i>Required Parts and Tools</i> (Added seals, bolts, and clips)

Workshop findings:

The following DTC is stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P045600** (Small EVAP leak)

Technical Background

Rubber O-ring at tank filler neck is out of position.

Production Solution

Improved rubber O-ring support.



Technical Service Bulletin

Service

1. Before proceeding, ensure that the gas cap was tight, and that the DTC is present.
2. Test for a leak by first calibrating tester KLI9210 to 0.02 inch port with 14 inch/water as described on the tester. Set marker on flow meter to this position and take a picture for documentation.
3. Block off the filter port on the NVLD sensor (Figure 1).



Figure 1. Block the filter port on the NVLD sensor.

4. Connect the tester to the vehicle and pressurize the system (3–5 minutes).
5. Take a picture of the flow meter.
6. Remove the purge line from the N80 valve.
7. Generate smoke with the smoke function of the KLI9210 tester until smoke comes out of the purge line on the N80 side.
8. Smoke EVAP system under pressure.



Technical Service Bulletin

9. • If smoke is escaping around the filler neck of the fuel tank (wheel liner removed) replace fuel tank (Figure 2).
- If no leak can be found, contact TAC.



Figure 2. Check for smoke escaping around the filler neck.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2010		
Damage Code:	0050		
Labor Operations:	Fuel tank remove + reinstall	2010 1950	160 TU
	Remove + reinstall sender and pump	2010 5550	90 TU
	Rear axle remove + reinstall	4205 19XX	See Elsa
	Brake system bleed	4701 0750	30 TU



Technical Service Bulletin

	Leak test and smoke EVAP system	2010 1999	20 TU
Diagnostic Time:	GFF – Checking and clearing fault codes	0150 0000	20 TU
	Road test before service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2044156/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.		
Part Number	Part Description	Quantity
4G0201060CB	Fuel Tank	01
N 10500802	Bolt	02
1J0919133B	Seal	01
WHT004756A	Bolt	02
WHT005800	Bolt	02
N 10772201	Clip	01
N 10719001	Bolt	06
4G0201317	Seal	01

Additional Information

All parts and service references provided in this TSB (2044156) are subject to change and/or removal.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in



Technical Service Bulletin

any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.