

Technical Service Bulletin



01 MIL on (DTC P1B1C); message in information panel: "Coolant System: Fault Turn Off Engine"

01 16 52 2040491/2 January 20, 2016. Supersedes Technical Service Bulletin Group 01 number 15-24 dated June 9, 2015 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2012 - 2015	All	3.0 T

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (Updated software version in SVM table) Revised <i>Warranty</i> (Updated Service Number; corrected TU)
1	6/9/2015	Initial publication

- MIL on.
- The following warnings appear in the information panel:
 - "Coolant System: Fault Turn Off Engine"
 - Coolant symbol (Figure 1)
- The following DTC is stored in the engine control module (ECM), J623 (address word 01):
 - **DTC P1B1C00** (Coolant pump mechanical malfunction)



Figure 1. Coolant symbol.

Technical Background

The condition is caused by one of the following scenarios:

- **Scenario A:** There is a defect with the thermostat (in model year 2012 and 2013 vehicles).
- **Scenario B:** The diagnostic software is incorrectly displaying the warning. No technical issue exists.

Production Solution

- **Scenario A:** Improved thermostat installed in production.
- **Scenario B:** The diagnostic software has been updated.

Technical Service Bulletin

Service

1. Check *Coolant Temperature* in freeze frame data:

Engine speed	958.0	1/min
Normed load value	13.33	%
Vehicle speed	107	km/h
Coolant temperature	102	°C
Intake air temperature	18	°C
Ambient air pressure	990	mbar

2.
 - If coolant temperature is 115°C or higher, **Scenario A** applies. Replace the thermostat and update the ECM software.
 - If coolant temperature is less than 115°C, **Scenario B** applies. Update the ECM software only.

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the ECM (J623) using the SVM action code as listed in the table below if necessary.

Model	Engine	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
A6, A7	3.0L TFSI	4G0907551A	All	4G0907551A	0010	02A210
		4G0907551D		4G0907551D	0006	
		4G0907551J		4G0907551J	0004	
A4, A5, A5 cabriolet	3.0L TFSI	8K5907551C	All	8K5907551E	0004	02A210
		8K5907551E		8K5907551E	0004	
		8K5907551F		8K5907551G	0007	
		8K5907551G				
A8	3.0L TFSI	4H0907551G	All	4H0907551G	0005	02A210

Technical Service Bulletin



Q5	3.0L TFSI	8R0907551E	All	8R0907551F	0007	02A210
		8R0907551F		8R0907551F	0007	
		8R0907551D		8R0907551G	0006	
		8R0907551A		8R0907551A	0003	
		8R0907551G		8R0907551G	0006	

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	For Scenario A: 1958 For Scenario B: 2470		
Damage Code:	0010		
Labor Operations:	For Scenario A:		
	Thermostat remove+reinstall (A6, A7, Q5)	1958 1991	250 TU
	Thermostat remove+reinstall (For A4, A5, A5 cabriolet)	1958 1991	270 TU
	Thermostat remove+reinstall (For A8)	1958 1991	220 TU
	Compressor remove+reinstall (For A6, A7, A8)	2114 1941	160 TU
	Compressor remove+reinstall (For A4, A5, A5 cabriolet, Q5)	2114 1941	190 TU
	Software update	2470 2599	40 TU
	For Scenario B:		
	Software update	2470 2599	40 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 30 TU)

Technical Service Bulletin



	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB # 2040491/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part number	Part Description	Quantity
06E121111AL	Thermostat (only if scenario A applies)	1
G 13A8J1G	Coolant	0.5

Additional Information

All parts and service references provided in this TSB (2040491) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.