



Service Bulletin

PRELIMINARY INFORMATION

Subject: Loss of Power Steering Assist Hard to Steer And/Or Service Power Steering Message On DIC

Models: 2015 Chevrolet Colorado
2015 GMC Canyon

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some Customers may comment of a loss of power steering assist, hard to steer or Service Power Steering message on the DIC. This concern may be intermittent.

Recommendation/Instructions

Check the PSCM for codes.

If code C056D is stored, reprogram the PSCM with the latest calibrations available in TIS2WEB.

If code C0545 is stored, please contact GM Technical Assistance for further direction.

For any other concerns, perform published diagnostics.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810625	Power Steering Control Module Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION