



Service Bulletin

INFORMATION

Subject: Engineering Information – Check Engine Light Illuminated and DTC P0751 Set on Vehicles Under 5,000 Miles

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado Suburban Tahoe	2016	2016			All	MYC
GMC	Sierra Yukon Models	2016	2016			All	MYC

Involved Region or Country	North America
Additional Options (RPO)	Equipped with 6 Speed Automatic Transmission (RPO MYC)
Condition	Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI. Some customers may comment on a check engine light illuminated. During diagnosis a technician may find DTC P0751 set.
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Correction

If you encounter a vehicle with the above concern and has less than 5,000 miles (8,000 km) with no magnetic debris is found in the bottom of the fluid pan, contact one of the engineers below before attempting any repairs.

Note: The engineer may request the control solenoid valve and transmission control module assembly returned undisturbed.

Contact Information

Engineer Name	Phone Number
Roman Shestakov	734-231-9455
Pete Bock	734-216-8854

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
8480558*	Engineering Information Call and Transmission Diagnosis for Debris Not Found in Pan	1.0 hr
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.		

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION