



SERVICE BULLETIN

Classification:

EC16-036

Reference:

NTB16-117

Date:

November 30, 2016

2016-2017 ALTIMA; MIL ON WITH A/F RATIO SENSOR DTC(s)

APPLIED VEHICLE: 2016-2017 Altima (L33)
APPLIED VIN: 2016: All
2017:
Vehicles built before 1N4AL3AP(*)HN 320032
Vehicles built before 1N4AL3AP(*)HC 150786
APPLIED DATE: Vehicles built before November 1, 2016
APPLIED ENGINE: QR25DE

IF YOU CONFIRM

One or more of the following DTCs is stored:

- **P014C** - A/F SENSOR1 (B1) (O2 sensor slow response - rich to lean bank 1 sensor 1)
- **P014D** - A/F SENSOR1 (B1) (O2 sensor slow response - lean to rich bank 1 sensor 1)
- **P015A** - A/F SENSOR1 (B1) (O2 sensor delayed response - rich to lean bank 1 sensor 1)
- **P015B** - A/F SENSOR1 (B1) (O2 sensor delayed response - lean to rich bank 1 sensor 1)

ACTION

1. Refer to step 6 in the **SERVICE PROCEDURE** to confirm this bulletin applies to the vehicle you are working on.

If this bulletin applies:

2. Reprogram the ECM.
3. Replace the Air Fuel Ratio (A/F) Sensor 1.

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

Reprogram the ECM

NOTE:

- Most instructions for reprogramming with CONSULT-III plus (C-III plus) are displayed on the CONSULT PC screen.
- If you are not familiar with the reprogramming procedure, [click here](#). This will link you to the "CONSULT- III plus (C-III plus) ECM Reprogramming" general procedure.
- Take the vehicle for a 10 minute drive in order to meet the following Idle Air Volume Learn (IAVL) conditions:
 - Engine coolant temperature: 70 -100°C (158 -212°F)
 - Battery voltage: More than 12.9V (At idle)
 - Transmission: Warmed up
- After reprogramming is complete, you will be required to perform Throttle Valve Closed Position, Idle Air Volume Learn, Accelerator Closed Position, and DTC erase.



Figure A

CAUTION:

- Connect the GR8 to the 12V battery and select ECM Power Supply Mode. If the vehicle battery voltage drops below 12.0V or above 15.5V during reprogramming, the ECM may be damaged.
- Be sure to turn OFF all vehicle electrical loads. If a vehicle electrical load remains ON, the ECM may be damaged.
- Be sure to connect the AC Adapter. If the CONSULT PC battery voltage drops during reprogramming, the process will be interrupted and the ECM may be damaged.
- Turn off all external Bluetooth® devices (e.g., cell phones, printers, etc.) within range of the CONSULT PC and the VI. If Bluetooth® signal waves are within range of the CONSULT PC during reprogramming, reprogramming may be interrupted and the ECM may be damaged.

1. Connect the CONSULT PC to the vehicle to begin the reprogramming procedure.
2. Start C-III plus.
3. Wait for the plus VI to be recognized / connected.
 - The serial number will display when the plus VI is recognized / connected.
4. Select **Re/programming, Configuration**.





Figure 1

5. Follow the on-screen instructions and navigate the C-III plus to the screen shown in Figure 2 on the next page.

6. When you get to the screen shown in Figure 2, confirm this bulletin applies as follows.

A. Find the ECM **Part Number** and write it on the repair order.

NOTE: This is the current ECM Part Number (P/N).



CONSULT-III plus Ver. VIN Vehicle : Country : U.S.A.

Back Home Print Screen Screen Capture Measurement Mode Recorded Data Help 11.8V VI MI 7/7

Re/programming, Configuration Operation Selection **Save ECU Data**

Save ECU Data

Touch "Save" to save operation log and the current part number as listed below to CONSULT. Operation log helps to restart next operation by selecting suitable operation log. Operation log is erased after operation has completely finished.

File Label	XXXXXXXXXXXXXXXXXX
Operation	REPROGRAMMING
System	ENGINE
Part Number	23710- _____
Vehicle	XXXXXXXXXXXXXXXXXX
VIN	XXXXXXXXXXXXXXXXXX
Date	11/1/2011 1:22:16 AM

Save

Figure 2

B. Compare the P/N you wrote down to the numbers in the **Current ECM Part Number** column in **Table A** on the next page.

- If there is a match, this bulletin applies. Continue with the reprogramming procedure.
- If there is not a match, this bulletin does not apply. Close C-III plus and refer to ASIST for further diagnostic information.

Table A


MODEL	CURRENT ECM PART NUMBER: 23710-
2016 Altima with QR25DE	9HN4A, 9HN4B, 9HN4C, 9HN4D, 9HN4E
	9HN5A, 9HN5B, 9HN5C, 9HN5D, 9HN5E
	9HN6A, 9HN6B, 9HN6C, 9HN6D, 9HN6E
	9HN7A, 9HN7B, 9HN7C, 9HN7D, 9HN7E
	9HN8A, 9HN8B, 9HN8C, 9HN8D, 9HN8E
	3TY2A, 3TY2B, 3TY2C, 3TY2D, 3TY2E
	3TY3A, 3TY3B, 3TY3C, 3TY3D, 3TY3E
	3TY4A, 3TY4B, 3TY4C, 3TY4D, 3TY4E
	3TY5A, 3TY5B, 3TY5C, 3TY5D, 3TY5E
	3TY9A, 3TY9B, 3TY9C, 3TY9D, 3TY9E
2017 Altima with QR25DE	9HL0A, 9HL0B
	9HL1A, 9HL1B
	9HL2A, 9HL2B
	9HL3A, 9HL3B
	9HL4A, 9HL4B

7. Follow the on-screen instructions to navigate C-III plus and reprogram the ECM.

NOTE:

- In some cases, more than one new P/N for reprogramming is available.
 - In this case, the screen in Figure 3 displays.
 - Select and use the reprogramming option that **does not** have the message “Caution! Use ONLY with NTBXX-XXX”.
- If you get this screen and it is blank (no reprogramming listed), it means there is no reprogramming available for this vehicle. Close C-III plus and refer back to ASIST for further diagnosis.

IMPORTANT: If C-III plus locks up or freezes at this point or displays “cannot complete reprogramming, CONSULT PC is set up with User Rights. Reprogramming can be completed with Administrator log in”, the TOUGHBOOK settings need to be changed so that Users have full access rights. See your Dealership’s IT System Administrator for details.



CONSULT-III plus Ver. VIN: Vehicle : Country : U.S.A.

Back Home Print Screen Screen Capture Measurement Mode Recorded Data Help

11.8V VI MI

Re/programming, Configuration Precaution **Select Program Data** Confirm Vehicle Condition 9/11

Select Program Data

Touch and select the reprog/programming data listed below.
In case no reprog/programming data is listed below, confirm the vehicle selection, VIN and reprog/programming data in CONSULT.

System ENGINE

Current Part Number	Part Number After Reprogramming	Other Information
XXXXX-XXXXX	XXXXX-XXXXX	XXXXXXXXXXXXXXXXXXXXX
XXXXX-XXXXX	XXXXX-XXXXX	XXXXXXXXXXXXXXXXXXXXX

0/0 Next

Figure 3

8. When the screen in Figure 4 displays, reprogramming is complete.

NOTE: If the screen in Figure 4 does not display (reprogramming does not complete), refer to the information on page 8.

9. Disconnect the battery charger from the vehicle.

10. Select **Next**.




Figure 4

NOTE:

- In the next steps, starting on page 9, you will perform Throttle Valve Closed Position, Idle Air Volume Learn, Accelerator Closed Position, and DTC erase.
- These operations are required before C-III plus will provide the final reprogramming confirmation report.

ECM recovery:

Do not disconnect plus VI or shut down Consult III plus if reprogramming does not complete.

If reprogramming does not complete and the “!?” icon displays as shown in Figure 5:

- Check battery voltage (12.0–15.5 V).
- Ignition is ON, engine OFF.
- External Bluetooth® devices are OFF.
- All electrical loads are OFF.
- **Select retry and follow the on screen instructions.**
- “Retry” may not go through on first attempt and can be selected more than once.




Figure 5

If reprogramming does not complete and the “X” icon displays as shown in Figure 6:

- Check battery voltage (12.0 – 15.5 V).
- CONSULT A/C adapter is plugged in.
- Ignition is ON, engine OFF.
- Transmission is in Park.
- All C-III plus / VI cables are securely connected.
- All C-III plus updates are installed.
- **Select Home, and restart the reprogram procedure from the beginning.**




Figure 6

11. Follow the on-screen instructions to perform the following:

- **Throttle Valve Closed Position.**
- **Idle Air Volume Learn (IAVL).**

NOTE:

- **Listed below are common conditions required for IAVL to complete.**
- **If IAVL does not complete within a few minutes, a condition may be out of range.**
- **Refer to the appropriate ESM for specific conditions required for the vehicle you are working on.**
 - Engine coolant temperature: 70 -100° C (158 -212°F)
 - Battery voltage: More than 12.9V (At idle)
 - Selector lever: P or N
 - Electric load switch: OFF (Air conditioner, headlamp, rear window defogger)
 - Steering wheel: Neutral (Straight-ahead position)
 - Vehicle speed: Stopped
 - Transmission: Warmed up
- **Accelerator Pedal Close Position Learning**
- **Erase DTCs**

Continue to the next page.

12. When the entire reprogramming process is complete, the screen in Figure 7 will display.

13. Verify the before and after part numbers are different.

14. Print a copy of this screen (Figure 7) and attach it to the repair order for warranty documentation.

15. Select **Confirm**.




Figure 7

16. Close C-III plus.

17. Turn the ignition OFF.

18. Disconnect the plus VI from the vehicle.

19. Replace the Air Fuel Ratio (A/F) Sensor 1.

- Refer to the Electronic Service Manual (ESM), section **EC – Engine Control / REMOVAL AND INSTALLATION / EXHAUST MANIFOLD AND THREE WAY CATALYST / Removal and Installation.**

PARTS INFORMATION

SPECIFICATION	DESCRIPTION	PART NUMBER	QUANTITY
50-State	Air Fuel Ratio (A/F) Sensor 1	22693-3TY0A	1
California		22693-3TA0A	1

CLAIMS INFORMATION

Submit a Primary Part (PP) line claim using the following claims coding:

DESCRIPTION	OP CODE	PFP	SYM	DIAG	FRT
Reprogram Engine Control Module	DE97AA	(1)	ZE	32	(2)
Replace One Air/Fuel Ratio Sensor	DE53AA				

(1) Refer to the electronic parts catalog (FAST) and use the Blank ECM assembly part number (23703-*****) as the Primary Failed Part (PFP).

(2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated flat rate time.