



Preliminary Information

PIP5646 Rear Wheels Lock Up While Driving At Low Speeds Feels Like The Brakes Applied Or The Transmission Was Shifted To Park DTCs P2724 P2727 Or P2729 May Or May Not Set

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	MQE
GMC	Sierra 1500 (New Model)	2019	All	All	All	MQE

Involved Region or Country	North America
Condition	Customers may comment that while driving at low speeds the rear wheels lock up and cause the vehicle to come to a stop as if the brakes were applied or the vehicle was shifted into park. DTC's P2727, P2729 or P2724 may be set but not in all situations. DTC's may have not set when this condition occurred. The customer may describe the condition occurred in the following situations: The vehicle was parked and allowed to hot soak. The vehicle is restarted. The transmission is shifted to drive. The vehicle will drive forward for a short distance and the wheels lock up. The transmission may stay in this condition for several key cycles and may be towed in for service. The transmission will have reverse. The vehicle is driven and then idled in park from 30 minutes to 4 hours. The transmission is shifted to drive. The vehicle will dive forward for a short distance and the wheels lock up. The transmission may stay in this condition for several key cycles and may be towed in for service. The transmission will have reverse.
Cause	Internal TCM

Correction:

Replace the TCM, part number 24289415 or 2429206. Reference [PIP5575A](#) and contact the PQC to obtain the TCM

Do not clear any DTC's from the TCM or perform a Service Fast Learn (SFL). Follow published Service Information procedures for the replacement of the TCM.

Parts Information

Description	Part Number	QTY
Transmission Control Module	Old 24289415	1
Transmission Control Module	New 24296206	1

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8461430	Transmission Control Module Replacement	Use Published Labor Time

Version History

Version	1
Modified	05/14/2019 - Created on

