



Technical Service Bulletin

90 Driver assist systems: parking aid, maneuver assist, rear cross-traffic assist not working (DTC U111000, U112300)

90 24 57 2074688/3 December 17, 2024. Supersedes Technical Service Bulletin Group 90 number 24-38 dated October 28, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, and Q8	2019 – 2025	All	Driver assist systems
e-tron	2019 2021 – 2023		
X`A6 allroad, S6, S7, S8, Q7, SQ7, SQ8, and RS Q8	2020 – 2025		
e-tron Sportback	2020 - 2023		
RS 6 Avant, and RS 7	2021 – 2025		
A7 e quattro	2021 – 2022		
e-tron GT, and RS e-tron GT	2022 – 2025		
Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024 – 2025		

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Service</i> (corrected software version listings)
2	10/28/20204	Revised header (Added MY 25 e-tron GT) Revised <i>Production Solution</i> (Updated software version and date) Revised <i>Service</i> (Added service measure for MY 2024 / 2025)



Technical Service Bulletin

1	07/27/2024	Initial publication
---	------------	---------------------

Customer states:

After passing through a toll booth or during heavy traffic (e.g., during rush hour), the customer complains about one or more of the following functional issues:

- The parking aid is not working. The following message appears in the instrument cluster: **“Parking aid: fault. Obstacles cannot be detected.”**
- The maneuver assist is not working. The following message appears in the instrument cluster: **“Maneuver assist: fault. Please contact workshop.”**
- The rear cross-traffic assist is not working. The following message appears in the instrument cluster: **“Rear cross-traffic assist: currently unavailable. See owner’s manual.”**

Workshop findings

The complaint occurs sporadically and usually cannot be reproduced.

The following DTCs (static / sporadic) may be stored in the following control units **with almost identical time stamps**. (The time stamps for the DTCs differ up to 5 seconds from each other)

Control unit for Information Electronics -J794- (address word 005F):

- **DTC U111000:** Function restriction due to communication interruption (**symptom 6922**).
- **DTC U111000:** Function restriction due to communication interruption (**symptom 7178**).

Driver assist systems control unit -J1121- (address word 00A5):

- **DTC U112300:** Data bus error value received (**symptom 2114053**).

Lane change assist control unit -J769- (address word 003C) (only when equipped with PR# 7Y1):

- **DTC U112300:** Data bus error value received (**symptom 1191978**).
- **DTC U112300:** Data bus error value received (**symptom 452352**).

Technical Background 1

Software issue.



Technical Service Bulletin

Production Solution

Optimized target data container for driver assist systems control unit -J1121- (diagnostic address 00A5) with software 0502 for week 40/2024.

Service

NOTICE

Please check the software version of driver assist systems control unit -J1121- (diagnostic address 00A5) and the model year of the vehicle **BEFORE** performing the service measure described here.

MY 2019/2020 and software version 0365

An update of the target data container is available for driver assist systems control unit -J1121- (diagnostic address 00A5). Please perform the **Check Control Module Configuration** test plan for driver assist systems control unit -J1121- (diagnostic address 00A5) with the ODIS tester. Follow the instructions on the tester.

MY 2021/2022/2023 and software versions 0364, 0365, 0366, 0371, 0381, 0383

A **software update** including an update of the target data container is available for driver assist systems control unit -J1121- (diagnostic address 00A5). Carry out the following steps with the ODIS tester:

CAUTION

Please make sure to change the communication method to "DoIP".

1. Changing communication method to DoIP:

- a. Admin --> General --> GFS Process.
- b. Select the communication path: "Only allow DoIP communication".

2. Software update for various driver assist system control units:

- a. Select "flash".



Technical Service Bulletin

- b. Select "SVM code input".
- c. Perform software update using SVM code **FASISKD6A002** (duration of update: approx. 15 – 100 minutes; varies depending on vehicle equipment).



CAUTION

After the message “Should the entered SVM code be accepted or the vehicle connection be changed?” is displayed, please double-check if vehicle access is set to DoIP. If it is not, please change it to DoIP by selecting “3. Change vehicle access (CAN, DoIP, CANFD)”.

Model years 2021/2022/2023 and software version 0384

An update of the target data container is available for driver assist systems control unit -J1121- (diagnostic address 00A5). Please perform the **Check Control Module Configuration** test plan for driver assist systems control unit -J1121- (diagnostic address 00A5) with the ODIS tester. Follow the instructions on the tester.

Model year 2024 and software version 0394

Update the driver assist systems control unit -J1121- (diagnostic address 00A5) with SVM. To enter the SVM code, use “Flash” mode on the ODIS tester. The SVM code is **A5A019**. Follow the instructions on the tester.

Model years 2024/2025 and software version 0502

An update of the target data container is available for driver assist systems control unit -J1121- (diagnostic address 00A5). Please perform a check control module configuration test plan for driver assist systems control unit -J1121- (diagnostic address 00A5) with the ODIS tester. Follow the instructions on the tester.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.
Service Number:	9093
Damage Code:	0039



Technical Service Bulletin

Labor Operations:	Without software update:		
	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol
	GFF / Guided Functions	0150 0010	See SRT with associated operations
	With Software update:		
	GFF / Guided Functions	0151 0060	Time stated on the diagnostic protocol
	GFF / Guided Functions	0151 0010	See SRT with associated operations
Claim Comment:	As per TSB 2074688/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2074688**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.